BEFORE THE TENNESSEE REGULATORY AUTHORITY NASHVILLE, TENNESSEE

IN RE:)		
)		
PETITION OF BERRY'S CHAPEL)		
UTILITY, INC. TO RECOVER COSTS)		
TO REPAIR FLOOD DAMAGE AND TO)		
REFUND CUSTOMER SERVICE FEES)	DOCKET NO.	11-00180

PETITION TO RECOVER COSTS TO REPAIR FLOOD DAMAGE AND TO REFUND CUSTOMER SERVICE FEES

Berry's Chapel Utility, Inc., f/k/a Lynwood Utility Corporation, petitions to Tennessee Regulatory Authority pursuant to T.C.A. § 65-5-201 and 202 to allow the company to impose a surcharge to recover extraordinary losses resulting from flood damage in May, 2010.

The flood damages are described in the attached letter (Exhibit A) dated May 21, 2010, from Tyler Ring, the president of Berry's Chapel, to TRA Chairman Sara Kyle. As stated in the letter, the flood damages were substantial and unprecedented:

All 13 treatment basins within Lynwood's treatment plant were flooded by five to seven feet of water. The influent pump station at the plant and one of the pump stations in Lynwood's collection system were completely submerged. Flood waters entered the entire building that houses the laboratory, electrical, chemical, storage and blower rooms and rose to approximately one foot throughout the building. Numerous pumps, control panels and motors in the building were completely submerged during the flood. Storage supplies were destroyed as well as backup systems, generators, lab supplies, etc.

There are also photographs of the flood damage shown in Schedule FD-1 (attached). The cost of repairs, less the amount of insurance money collected, is \$190,237. These expenses are itemized in Schedule FD-1. Berry's Chapel proposes to recover the cost of repairs over three

¹ See Schedule FD-1 for a calculation of the net deferred amount. The amount includes \$48,766.42 in expenses for flood damage repairs that have not yet been made. The cause of these damages and the need for repairs is discussed in the attached letter to James Ford from G.A.M. Engineering, Inc. Exhibit B.

years. Based on estimated annual usage of 72,570,000 gallons,² the utility could recover \$190,237 by imposing a surcharge of \$0.87 per 1,000 gallons for a three-year period.

At the same time, Berry's Chapel proposes to refund to its customers the "service fees" collected in 2010 and 2011. The Authority ordered these refunds in Docket 11-00005, issued August 5, 2011.³ Berry's Chapel collected \$69,866 in service fees from its customers. The utility billed, but did not collect, an additional \$14,514 in service fees. Following discussions with the TRA staff and the Consumer Advocate and Protection Division, the utility has not tried to collect those unpaid fees.

Berry's Chapel does not have the financial ability to make a cash refund of the service fees.⁴ To comply with the Authority's <u>Order</u>, the utility will refund the service fees by deducting the total amount of service fees collected from the costs of the flood repairs. As shown on Schedule FD-1, this reduces the proposed surcharge from \$0.87 to \$0.55 per 1,000 gallons over a three-year period.

² This usage estimate is based on actual usage during the period of July 1, 2010 through June 30, 2011, as shown in the company's recently filed annual report.

³ Although the utility has appealed the <u>Order</u>, the utility will comply with the Authority's directions pending judicial review.

⁴ As reflected in the company's annual report recently filed with the Authority, Berry's Chapel lost \$341,181 during the ten-month period ending June 30, 2011.

Berry's Chapel therefore asks that the Authority approve an amendment to the utility's tariffs to allow the utility to collect a flood damage surcharge of \$0.55 per 1,000 gallons of usage for three years and to approve the utility's proposal to refund the "service fees," as directed by the TRA's Order in Docket 11-00005, through a reduction in the surcharge amount.

Respectfully submitted,

BRADLEY ARANT BOULT CUMMINGS LLP

By:

Henry Walker (B.P.R. No. 000272)
Bradley Arant Boult Cummings, LLP

1600 Division Street, Suite 700

Nashville, TN 37203 Phone: 615-252-2363 Email: hwalker@babc.com

cc: Vance Broemel

Consumer Advocate and Protection Division, Office of the Attorney General

LYNWOOD UTILITY CORPORATION 321 BILLINGSLY COURT, SUITE 4 FRANKLIN, TN 37067 PHONE: 615/790-3632 FAX: 615/599-0797

May 21, 2010

Sara Kyle, Chairman Tennessee Regulatory Authority 460 James Robertson Parkway Nashville, TN 37243-0505

Re: Lynwood Utility Corporation – Report on Flood Damage

Dear Chairman Kyle:

I am writing you to inform the Tennessee Regulatory Authority of the effects of the recent flooding on Lynwood Utility Corporation's sewer treatment and collection system. Lynwood's plant is located immediately adjacent to the Harpeth River just south of Franklin and discharges its effluent into the Harpeth River.

During the heavy rains that began on May 1, 2010, Lynwood's sewer treatment plant and portions of its collection were badly flooded. All systems at the plant became non-operational at approximately 6:00 p.m. on Saturday, May 1st. All 13 treatment basins within Lynwood's treatment plant were flooded by five to seven feet of water. The influent pump station at the plant and one of the pump stations in Lynwood's collection system were completely submerged. Flood waters entered the entire building that houses the laboratory, electrical, chemical, storage, and blower rooms and rose to approximately one foot throughout the building. Numerous pumps, control panels, and motors in the building were completely submerged during the flood. Storage supplies were destroyed as well as backup systems, generators, lab supplies, etc.

I assembled a disaster response team to assess damages and to get the sewer plant back in operation as quickly as possible. The disaster response team began its work at approximately 5:00 a.m. on Monday, May 3rd which was the first moment a vehicle could safely reach the plant because of extensive flooding in the Cottonwood Subdivision. The disaster response team included all available staff of Lynwood's operations and maintenance contractors and approximately 15 persons who work for Tenn. Contractors Inc. Personnel from Southern Sales Company, which sells and services electrical equipment used in the plant were called in on Monday morning. Communications and correspondence began taking place with personnel of the following entities: City of Franklin, Williamson County, Heartland Pump Company, Metro

Sara Kyle, Chairman May 21, 2010 Page 2

Nashville, the Tennessee Department of Environment and Conservation (TDEC), Middle Tennessee Electric Membership Cooperation (MTEMC) and The National Weather Service. I contacted Atlas Septic Service, Waste Management, and Sani-tech Jetvac Services and put them on standby in case I needed their assistance.

The sewer treatment plant remained non-operational until a flooded diesel pump began working at approximately 10:30 a.m. on Monday morning which permitted partial operations to begin. Power was restored to the plant at approximately 12:30 p.m. that same day. Heavy equipment began arriving to cleanup the plant site on Monday morning. The advanced treatment processes at Lynwood were restored by 1:00 a.m. Tuesday morning. Later Tuesday morning Lynwood began its lengthy process of cleaning all 13 treatment basins, repairing and cleaning the entire five acre site, as well as continuing to address the damage inside the building. Crews were continuing to monitor our pump stations because some of them were operating with no backup systems which were damaged by the flood.

I began making phone calls to assess the situation and made several unsuccessful attempts to get to the plant beginning on Saturday evening and continuing all day Sunday but was unable to do. Either myself or crews assembled by me were at the treatment plant around the clock from 5:00 a.m. Monday morning until early Wednesday morning. I was there the majority of this time period. Lynwood has spent approximately \$100,000 to get the plant operational and to begin the process to cleanup, repair and restore the sewer plant and collection system. I cannot currently give the Authority an accurate estimate of the total costs will be required to restore the sewer system to its prior condition. Nevertheless, considering the disaster response, partial operation, full scale operation, cleanup, long term damage and future preparation and restoration to both the plant and the collection system, my initial estimate is that the total costs will be in excess of \$500,000.

Lynwood is seeking to obtain all of the funds it can to reimburse it for damages caused by the flood. Lynwood did have flood insurance, but the insurer has currently verbally denied all claims for damage outside the building on the plant site. Much of the damage to the sewer plant was not within the building on the plant site. Lynwood has contracted with National Fire Adjusters to represent it in negotiating its claim with the flood insurance carrier to obtain more of a recovery based upon specific language in the policy. Lynwood has contacted the Federal Emergency Management Agency (FEMA) about grants available for public utilities for damages suffered as a result of the flood. FEMA has encouraged Lynwood to make application to the

Sara Kyle, Chairman May 21, 2010 Page 3

Small Business Administration (SBA) for a loan to cover the cost of flood damages and that application will be submitted shortly.

Although Lynwood's plant was non-operational for approximately 36 hours, the quick response by Lynwood resulted in minimal sewer service interruptions to its customers. Lynwood has received only no complaints about sewer service failures. Lynwood has not received any communications from the Authority about complaints related to service failures.

Until Lynwood is able to determine the amount and types of financial aid it will receive to cover the costs of the flood damages, I will make no decision about any actions which may be required to recover its costs incurred in the cleanup, repair and restoration of its sewer system from its ratepayers. If you or the Authority staff have any questions about the flood damage, please do not hesitate to contact me.

c;

Darlene Standley Richard Collier Ryan McGehee Don Scholes

G.A.M. Engineering, Inc.

CIVIL ENGINEERING

PO Box 303

Phone/Fax: 615-885-6278

Hermitage, TN 37076-0303

September 6, 2011

Mr. James B. Ford Visions, Inc. 9679 Aurora Court Brentwood, TN, 37027

RE: Berry's Chapel Utility Inc. GAM Project No. 11-077

Dear Mr. Ford,

The Berry's Chapel Waste Water Sewage Plant was constructed in 1976 to serve the Cottonwood Subdivision. The original plant is a packaged type plant, originally designed to treat 0.125 MGD sewage flow. It is constructed of pre-cast concrete sections and contained two aeration basins, sludge digester, clarifier, and chlorine contact chamber. The plant operated in this way until Phase 1 plans were completed in 1996 which expanded the plant from 0.125 MGD to 0.200 MGD to serve the Legends Ridge Subdivision development. The Phase 1 expansion included the installation of a 40 foot diameter clarifier, reworking the existing aeration headers, and expanding the chlorine contact chamber. Phase 2 plans were completed in 1998 which expanded the plant from 0.200 MGD to 0.400 MGD to serve additional developments in there service area. The Phase 2 expansion included the construction of two new concrete aeration basins, installation of fine bubble air diffusion in the two existing aeration basins, installation of a new outfall to the Harpeth River, upgrading the chlorine and sodium dioxide feed systems, installation of new influent bar screen, flow splitter basin, installation of new sludge handling equipment and sludge drying box for disposal of the sludge to an approved landfill. Phase 3 plans were prepared in 2003, which is the last expansion of the plant to date. The Phase 3 expansion converted the plant to a two-stage nitrification/denitrification process. The Phase 3 expansion included the construction of a two chamber basin for the nitrification/denitrification process, installation of a new 40 foot diameter clarifier to use for secondary treatment, miscellaneous piping and electrical upgrades. No additional upgrades or expansions have been done to the waste water plant since the last expansion of 2003.

In the late 1990's, the plant had numerous NPDES permit violations incurring fines from the State and causing the State to impose a moratorium on sewer connections until the plant was in compliance with there permit. Since 2002 and the last plant expansion in 2003 NPDES violations have decreased substantially and the plant is currently operating and meeting all there limits as required per there current NPDES permit. It was the plant expansions and hiring capable and knowledgeable plant operators by Berry's Chapel Utility Inc., that have made this plant operate as it was originally designed.

Mr. James B. Ford Visions, Inc. September 6, 2011 Page 2 of 3

In May of 2010 we experienced a record rainfall that produced the equivalent of a 500 year storm event. The flooding that occurred at the sewage treatment plant washed out the entire plant as water was approximately 4 to 5 feet over all the structures. This also washed out the influent pump station, that pumps all incoming sewage up to the treatment plant, as well as flooding of the control building. After the flood waters receded work immediately began by the company to restore the sewage treatment process. All the basins, clarifiers, and influent pump station were pumped out, cleaned and put back into service on a temporary basis. The control building housing the electrical equipment, blowers, disinfection equipment and laboratory was cleaned and repaired to temporarily operate the plant until more permanent repairs can be made. The control building walls were also damaged by the flood and will need to be repaired to make the building structurally sound. The company's insurance provider made an inspection of the damage after the flooding and paid for very little of the cleanup or repairs as the policy did not cover major flooding that was not under roof. The company has implemented repairs to keep the plant operating efficiently and to meet the effluent permit limits that are set out in there current NPDES Operating Permit and future limits that will be imposed.

Berry's Chapel Utility Inc. current NPDES Operating Permit will expire in November 2011. A new application/permit has been submitted to the State and is currently under review. From conversations we have had with the State it is very possible that stricter effluent discharge limits will be a reality on the newly issued NPDES Operating Permit. Due to the flooding that occurred last year and the repairs that were made, to bring the plant back into operation, were mostly temporary repairs and will need to be made permanent repairs in order for the plant to operate efficiently and meet there current and future NPDES Operating Permit limits. In order for Berry's Chapel Utility to make the permanent repairs there options are; 1) Raise current sewer rates to cover the construction costs, 2) Obtain a low interest loan or grant from a State program or borrow money from a bank, 3) A combination of a rate increase and obtaining a loan. In either option a hard look will need to be made at the current sewer rate structure to insure that the Berry's Chapel Utility can continue to operate and to have enough funds to keep qualified operation personnel employed and to make necessary improvements as there NPDES Operating Permit limits change. Since the majority of the repairs that were made after the flooding were temporary it won't be long in the future where these repairs will start causing problems and effect the operation of the plant.

The current sewage treatment plant is now over 35 years old and the technology that was used in 1976 to design the sewage plant is now obsolete. With stricter treatment standards imposed on all sewage treatment operations it is imperative that the sewage treatment plant be continuously upgraded to meet current and future treatment requirements. The life of the plant is now approaching its design life of 40 to 50 years, therefore it is of the utmost importance that Berry's Chapel Utility start planning now for upgrades to the plant instead of waiting for more serious issues to develop. With construction costs increasing dramatically each year it is better to make the necessary repairs and improvements as soon as possible. Once the permanent repairs have been made it will help keep the plant operating efficiently

Mr. James B. Ford Visions, Inc. September 6, 2011 Page 3 of 3

for another 30 years. However as with all mechanical equipment breakdowns will occur and the equipment will have to be repaired or replaced. These replacement costs will be minor compared to having to make structural repairs to the concrete basins and control building if left to deteriorate over the remaining design life of the plant.

If you have any questions or would like to meet and discuss please feel free to contact me.

Sincerely,

G.A.M. Engineering, Inc.

Gregg M. Clingerman, P.E.


Cc: Tyler Ring


BERRY'S CHAPEL UTILITY, INC.	SCHEDULE FD-1
DEFERRED COST - FLOOD DAMAGE 2011	
DEFERRED COST FLOOD DAMAGE	\$190,237
LESS: FACILITY CHARGES BILLED	(\$84,380)
FACILITY CHARGES NOT PAID BY CUSTOMERS	\$14,514
	(\$98,866)
NET BALANCE TO RECOVER	\$120,371
RECOVERY PERIOD (3 years)	\$40,124
DIVIDED BY: ANNUAL VOLUME	72,570
	\$0.55 per 1,000 gallons


BERRY'S CHAPEL UTILITY, INC


DEFFERED FLOOD DAMAGE

1)	Summary Expense Report		\$	26,729.24
2)	Southern Sales		\$	23,229.58
3)	Repaired and Cleaned Float Telemetry		\$	3,450.00
4)	Replace Lab Equipment		\$	3,019.21
5)	Grounds Cleanup and Repair		\$	33,000.00
6)	Pump Replacement		\$	613.11
7)	Detailed Inspection of 104 Manholes			
•	In Cottonwwood Subdivision and above			
	Ground inspection of 25,000 LF of			
	Collection System Lines		\$	1,875.00
8)	Replace Supplies Flood Damaged		\$	1,550.20
9)	Plant Basin #1 & #2 Cleaning and Repair		\$	8,400.00
10)	Pump & Haul from Basins		\$	7,450.00
11)	Building Cleanup & Repair		\$	3,500.00
12)	Concrete Work		\$	8,700.00
		SUB TTL	\$	121,516.34
	Overhead Capitalized (20%)		\$	24,303.27
		SUB TTL	\$	145,819.61
13)	Less Insurance Proceeds		-35	(28,214,43)
		SUB TTL	\$	117,605.18
	Interest for 18 months (8%) (6/1/10 to 12/1/11)		\$	14,112.48
		SUB TTL	\$	131,717.66
14)	Items Required to be repaired when funds are available		\$	48,766.42
	Overhead Capitalized (20%)	_	\$	9,753.28
	TOTAL FLOC	DD DAMAGE	\$	190,237.36
		=		





























Lynwood Utility Corporation

May 1st, 2010 Flood

Re: Timeline of events

Date: 5/13/2010

During the flooding event that began on May 1st, 2010 the Lynwood Utility Corporation lost total control of the plant at approximately 6:00 pm. All systems were non operational until a flooded diesel pump began working at approximately 10:30 am on Monday May 3rd, 2010. Power was restored to the plant by approximately 12:30pm that same day. Numerous amounts of pumps, control panels, and motors had been completely submerged during the flood. The influent Pump Station at the plant as well as one of the pump stations in Lynwood's collection system had been completely submerged. Flood waters had also entered the entire building that contains the laboratory, electrical, chemical, storage, and blower rooms. All 13 treatment basins within Lynwood's treatment plant had been flooded by 5 to 7 feet. The building had approximately 1 foot of water. Storage supplies were destroyed as well as backup systems, generators, lab supplies, etc.

The Disaster Response began at approximately 5:00am Monday (the first moment a vehicle could safely reach the plant) which included all of Lynwood's available staff as well as approximately 15 members of Tenn. Contractors Inc. staff. Personnel from Southern Sales Company were also present Monday morning. Correspondence was taking place with members of: City of Franklin, Williamson County, Heartland Pump Co., Metro Davidson County, Tennessee Department of Environment and Conservation (TDEC), Middle Tennessee Electric Membership Cooperation (MTEMC), and The National Weather Service. Atlas

Septic Service, Waste Management, and Sani-tech Jetvac Services were all put on standby.

Partial operation began at 10:30am Monday and power was restored at 12:30pm Monday, the Advanced Treatment processes at Lynwood were restored by 1:00am Tuesday morning. Later Tuesday morning Lynwood began the approximate two week process of cleaning all 13 treatment basins, repairing and cleaning the entire 5 acre site, as well as continuing to address the damage inside the building. Crews were continuing to monitor our pump stations as some of them were operating with no backup systems. Heavy equipment began arriving for the cleanup portion as early as Monday morning.

There appears to be no way (currently) to estimate just how much damage was associated with this event. However, considering disaster response, partial operation, full scale operation, cleanup, long term damage and future preparation to both the plant and the collection system the initial estimate should be in the range of \$500,000.00 plus. Lynwood did have flood insurance and currently has a verbal denial on all claims outside the building. Lynwood has obtained National Fire Adjusters to represent them on some discrepancies to their coverage. Lynwood is also researching the availability of Federal Emergency Management Agency (FEMA) Grants as well as Small Business Administration (SBA) Loans.

Thank you for your time and attention to this matter. Lynwood will be glad to answer any questions that may arise to help expedite financial aid to our business.

Sincerely,

Tyler Ring

President Lynwood Utility Corporation



LYNWOOD UTILITY CORPORATION 321 BILLINGSLY COURT, SUITE 4 FRANKLIN, TN 37067 PHONE: 615/790-3632 FAX: 615/599-0797

May 21, 2010

Sara Kyle, Chairman Tennessee Regulatory Authority 460 James Robertson Parkway Nashville, TN 37243-0505

Re: Lynwood Utility Corporation - Report on Flood Damage

Dear Chairman Kyle:

I am writing you to inform the Tennessee Regulatory Authority of the effects of the recent flooding on Lynwood Utility Corporation's sewer treatment and collection system. Lynwood's plant is located immediately adjacent to the Harpeth River just south of Franklin and discharges its effluent into the Harpeth River.

During the heavy rains that began on May 1, 2010, Lynwood's sewer treatment plant and portions of its collection were badly flooded. All systems at the plant became non-operational at approximately 6:00 p.m. on Saturday, May 1st. All 13 treatment basins within Lynwood's treatment plant were flooded by five to seven feet of water. The influent pump station at the plant and one of the pump stations in Lynwood's collection system were completely submerged. Flood waters entered the entire building that houses the laboratory, electrical, chemical, storage, and blower rooms and rose to approximately one foot throughout the building. Numerous pumps, control panels, and motors in the building were completely submerged during the flood. Storage supplies were destroyed as well as backup systems, generators, lab supplies, etc.

I assembled a disaster response team to assess damages and to get the sewer plant back in operation as quickly as possible. The disaster response team began its work at approximately 5:00 a.m. on Monday, May 3rd which was the first moment a vehicle could safely reach the plant because of extensive flooding in the Cottonwood Subdivision. The disaster response team included all available staff of Lynwood's operations and maintenance contractors and approximately 15 persons who work for Tenn. Contractors Inc. Personnel from Southern Sales Company, which sells and services electrical equipment used in the plant were called in on Monday morning. Communications and correspondence began taking place with personnel of the following entities: City of Franklin, Williamson County. Heartland Pump Company, Metro

Sara Kyle, Chairman May 21, 2010 Page 2

Nashville, the Tennessee Department of Environment and Conservation (TDEC), Middle Tennessee Electric Membership Cooperation (MTEMC) and The National Weather Service. I contacted Atlas Septic Service, Waste Management, and Sani-tech Jetvac Services and put them on standby in case I needed their assistance.

The sewer treatment plant remained non-operational until a flooded diesel pump began working at approximately 10:30 a.m. on Monday morning which permitted partial operations to begin. Power was restored to the plant at approximately 12:30 p.m. that same day. Heavy equipment began arriving to cleanup the plant site on Monday morning. The advanced treatment processes at Lynwood were restored by 1:00 a.m. Tuesday morning. Later Tuesday morning Lynwood began its lengthy process of cleaning all 13 treatment basins, repairing and cleaning the entire five acre site, as well as continuing to address the damage inside the building. Crews were continuing to monitor our pump stations because some of them were operating with no backup systems which were damaged by the flood.

I began making phone calls to assess the situation and made several unsuccessful attempts to get to the plant beginning on Saturday evening and continuing all day Sunday but was unable to do. Either myself or crews assembled by me were at the treatment plant around the clock from 5:00 a.m. Monday morning until early Wednesday morning. I was there the majority of this time period. Lynwood has spent approximately \$100,000 to get the plant operational and to begin the process to cleanup, repair and restore the sewer plant and collection system. I cannot currently give the Authority an accurate estimate of the total costs will be required to restore the sewer system to its prior condition. Nevertheless, considering the disaster response, partial operation, full scale operation, cleanup, long term damage and future preparation and restoration to both the plant and the collection system, my initial estimate is that the total costs will be in excess of \$500,000.

Lynwood is seeking to obtain all of the funds it can to reimburse it for damages caused by the flood. Lynwood did have flood insurance, but the insurer has currently verbally denied all claims for damage outside the building on the plant site. Much of the damage to the sewer plant was not within the building on the plant site. Lynwood has contracted with National Fire Adjusters to represent it in negotiating its claim with the flood insurance carrier to obtain more of a recovery based upon specific language in the policy. Lynwood has contacted the Federal Emergency Management Agency (FEMA) about grants available for public utilities for damages suffered as a result of the flood. FEMA has encouraged Lynwood to make application to the

Sara Kyle, Chairman May 21, 2010 Page 3

Small Business Administration (SBA) for a loan to cover the cost of flood damages and that application will be submitted shortly.

Although Lynwood's plant was non-operational for approximately 36 hours, the quick response by Lynwood resulted in minimal sewer service interruptions to its customers. Lynwood has received only no complaints about sewer service failures. Lynwood has not received any communications from the Authority about complaints related to service failures.

Until Lynwood is able to determine the amount and types of financial aid it will receive to cover the costs of the flood damages, I will make no decision about any actions which may be required to recover its costs incurred in the cleanup, repair and restoration of its sewer system from its ratepayers. If you or the Authority staff have any questions about the flood damage, please do not hesitate to contact me.

The Discount of the Control of the C

Darlene Standley
Richard Collier
Ryan McGehee
Don Scholes

CIVIL ENGINEERING

P.O. Box 303

Phone/Fax: 615-885-6278

Hermitage, TN 37076-0303

June 17, 2010

Mr. Tyler Ring, Owner Lynwood Utility Corporation 321 Billingsly Court, Suite 4 Franklin, TN. 37076

RE:

Lynwood Sewage Treatment Plant

Flood Damage Inspection GAM Project No. 10-054

Dear Mr. Ring,

Per your request an on site inspection was made at the sewage treatment plant on June 3, 2010. The purpose of the inspection was to determine the structural damage to the plant caused by the flooding which occurred on May 1st and 2nd, 2010. It has been reported by various agencies that the storms were classified as back to back 100-year floods and other agencies have reported that the two day storm event was classified as a 500-year plus flood.

Physical Plant

The Lynwood Utility Corporation is a private sewerage provider for the residents located in the Cottonwood, River Landings, Legends Ridge, Farmington and Chapelwood subdivisions in the northwesterly portion of Williamson County, Tennessee. The utility currently has approximately 820 sewer customers with all customers consisting of single family residences except for one customer which is an elementary school. Sewage is conveyed to the sewage treatment plant by gravity sewers, 2 sewage pump stations located in River Landings subdivision and 1 sewage pump station located in the Legends Ridge subdivision. All sewage from the pump stations flows through a force main system and discharges into the gravity sewer lines.

The sewage flows by gravity to the sewage treatment plant and enters the sewage treatment plant through a below ground sewage pump station. Raw sewage is pumped from the influent sewage pump station through a force main and discharges into the influent trench for gravity flow through the plant and for the treatment of the raw sewage prior to be discharged. The sewage flows through a bar screen which removes large pieces of debris out of the sewage flow and passes through the influent control weir with the incoming sewage flow being measured by the influent flow meter The sewage flows through a flow splitter box in which the sewage can be directed to any of the four aeration basins for treatment. Two of the aeration basins are supplied oxygen by four floating aerators (two per basin) and the other two aeration basins are supplied oxygen by a diffused air system. Two blowers and motors are located in the main control building to supply the necessary oxygen to the diffused air systems. The sewage flows from the aeration basins into the primary clarifier for the settlement of particles out of the sewage flow. The sewage then flows into the anoxic basin for the reduction of ammonia and nitrates in the treated sewage flow stream. The treated waste stream then flows to the chlorine/dechlorination chamber for the disinfection of the treated waste water prior to being

Mr. Tyler Ring, President Lynwood Utility Corporation June 17, 2010 Page 2 of 7

discharged into the Harpeth River through the outlet weir and effluent flow meter. See Appendix A for schematic of the existing sewage treatment plant layout and flows.

The main control building consists of the laboratory room, electrical room which houses the main electrical control panels for the incoming and standby power sources along with the blower motors and blower units and the blower control panel. The chlorine room houses the 150 pound Cl² cylinders and flow regulators for the disinfection of the treated waste water. The sodium dioxide room houses the 150 pound SO² cylinders and flow regulators for the dechlorination of the treated waste water prior to the discharge into the Harpeth River. The control building also houses the influent/effluent samplers and the polymer tank and polymer feed system for use in sludge disposal. A 200kw standby generator with automatic transfer switching provides power to the plant during electrical failures. The generator is located outside of the building with the electrical switch gear and controls mounted inside the main control building.

All the above mentioned items that are associated with the physical plant are all inter-connected by the sewage flow into and through the sewage treatment plant. The piping ties all the basins together and ties the control building to the remainder of the plant as the control building contains the influent/effluent samplers, electrical power to all of the plant, blowers to supply oxygen to the aeration basins and to the treated waste water prior to discharge into the Harpeth River, chlorination/dechlorination equipment, influent/effluent flow meter controls, and a laboratory for daily testing of the waste water. Therefore with out the control building the Lynwood sewage treatment plant could not operate as originally designed or as it is intended to operate currently to provide clean, treated waste water to meet State and Federal discharge standards. If one or more items are eliminated from the above process then the plant could not operate and treat incoming sewage as was experienced during the flooding events of May 1st and 2rd, 2010.

Off Site Sewage Pump Stations - Flood Damage

Lynwood Utility Corporation operates three sewage pump stations to transport sewage to the treatment plant. Two pump stations are located within the River Landings Subdivision. Each pump station has two suction lift type pumps where the controls, pumps and motors are housed in a fiberglass structure at grade. The Legends Ridge pump station consists of a wet well with two submersible sewage pumps. The controls are housed above grade in a water tight enclosure exposed to the elements. The Lynwood sewage treatment plant influent pump station is an underground steel can type unit. It consists of two horizontal dry well sewage pumps with the pumps and motors located in the can unit. The controls are located above grade in a water tight enclosure and are exposed to the elements.

One of the River Landings sewage pump station was submerged by the flood waters. The submergence of the station caused damage to the electrical controls and to the pump motors. Both motors had to be removed and cleaned of mud and debris and the motors had to be dried out and rewound. The electrical controls had to be dried out and new wiring installed.

Physical Plant Flood Damage

A. Influent Pump Station

The influent pump station was totally submerged by the flood waters. The two vertical dry well sewage pumps sucked up mud and debris into the impellers thus causing them to lock up and

Mr. Tyler Ring, President Lynwood Utility Corporation June 17, 2010 Page 3 of 7

burn up the bearings. The flood waters also shorted out and burnt up both motors. The control panel that was located outside of the pump station was also flooded causing the circuits to short out. The pumps and motors had to be removed and sent out to be reworked to remove the mud and debris, motors had to be dried out and the motors rewound. The control panel circuits had to be dried out and some circuit boards and wiring had to be replaced. Some of the soil under the concrete pad which is the top cover over the influent wet well has been washed out. The pad has cracked and a new concrete pad will need to be installed. Since the existing access hatch can not be salvaged from the existing concrete a new aluminum access hatch will need to be installed. Prior to the installation of the concrete pad and access hatch additional stone material will need to be brought in and compacted under the pad area to prevent the new pas from settling and possibly cracking or breaking.

B. Influent Flow Meter Transponder

The transponder for the influent flow meter was submerged. The transponder unit is not designed to be water tight or operate in the submerged condition. The transponder had to be removed and replaced.

C. Flow Splitter Box

The flow splitter box was submerged and was filled with mud and debris. The box had to be pumped out and the mud and debris had to be removed.

D. Aeration Basins

The sewage treatment plant consists or four aeration basin, two basins use submerged fine air diffused aerators and two of the basins utilize four floating aerators, two aerators per basin. All of the aeration basins were submerged by the flood water. All four aeration basins had to be pumped out, and debris and mud cleaned out of each basin.

Two of the basins have submerged fine air bubble diffused aerators installed in them. The aerator system consists of stainless steel piping, a diffused piping grid network which consists of hooded diffusers that have rubber diaphragm baffles that produce the fine air bubbles that are delivered into the waste water for the treatment and removal of the solids. The mud and debris damaged some of the stainless steel air piping, and debris damaged some of the butterfly valves stems, that control air flow to the diffusers, so that they will not open or close as designed. Approximately 250 of the rubber diaphragms had to be replaced as the mud and debris damaged the o-ring seals or the diaphragm itself.

Two of the basins have floating aerators installed in them with each basin containing two aerators. The floating aerators are designed to float on the water surface and aerate the waste water by forcing air down through a draft tube to the bottom of the basin which produces the oxygen needed for the treatment and removal of the solids. The floating aerators are tethered in place by stainless steel cables so that they remain centered and spaced equally in each basin. The mud and debris had to be cleaned out of both basins and mud had to be cleaned out of the draft tubes. The motors were submerged and all four motors will have to be cleaned, dried out and the wring rewound. The control panel circuit boards and wiring were damaged and the circuit boards and wiring will need to be replaced to make the panel operational.

Mr. Tyler Ring, President Lynwood Utility Corporation June 17, 2010 Page 4 of 7

E. Primary Clarifler

The primary steel clarifier was submerged by the flood waters. The clarifier had to be pumped out to remove the mud and debris that collected inside the clarifier. The water level in the clarifier is controlled by a series of weirs that encompass the interior outer perimeter of the clarifier. Debris that collected on the weir plate's damaging some of the sections of the weirs. The damaged sections had to be replaced to make the discharge of the waste water out of the weirs operate evenly around the entire perimeter of the clarifier. The motor to drive the clarifier scrapper was submerged and the motor had to be dried out and the motor wiring re-wound.

F. Anoxic Basins

The anoxic basins were submerged by the flood waters. Both basins had to be pumped out to remove the mud and debris that collected in the basins. The alum feed system was damaged and had to be replaced. The three (3) LMI metering pumps which control the feed of ethanol into the polishing basin were submerged. The metering pumps are not designed operate in a submerged condition; therefore all three pumps had to be replaced.

G. Secondary Clarifier

The secondary concrete clarifier, motor and control panel was submerged by the flood waters. The clarifier had to be pumped out to remove the mud and debris that collected inside the clarifier. The water level in the clarifier is controlled by a series of weirs that encompass the interior outer perimeter of the clarifier. Debris that collected on the weir plates damaging some of the sections. The damaged sections had to be replaced to make the discharge of the waste water out of the weirs operate evenly around the entire perimeter of the clarifier. The motor to drive the clarifier scrapper was submerged and the motor had to be dried out and the motor wiring rewound. The control panel had to be dried out and the wiring and some circuit boards replaced.

H. Chlorine Contact Chamber

The chlorine contact chamber was submerged by the flood waters. The basin had to be pumped out to remove the mud and debris that collected inside the basin. The transponder for the effluent flow meter was submerged. The transponder unit is not designed to be water tight or operate in the submerged condition. The transponder had to be removed and replaced.

I. Handrail System

The handrails around the diffused aeration basins, chlorine contact chamber, around the control building were damaged by floating debris. Some of the handrail sections got torn out while others handrail support piping was broken loose from there anchor in the concrete walkways. All handrail sections that were damaged or broken loose will need to be replaced as the missing sections will be a safety hazard for personnel working at the plant.

J. Miscellaneous Items

Do to the additional water pressure on the walls of the pre cast aeration basins and floating and submerged debris hammering the walls of the pre cast concrete aeration basins, leaking of the basins were discovered where the pre cast panels join together. The seams had to be repaired using a high strength epoxy to make the structure water tight before they could be put back into operation.

Mr. Tyler Ring, President Lynwood Utility Corporation June 17, 2010 Page 5 of 7

All electrical outlets, circuit breaker panels and equipment control panels, except for the steel clarifier control panel, were submerged by the flood waters. The outlets, circuit breaker panels and control panels had to be dried out, rewired, and circuit boards replaced as need prior to putting the plant back into operation.

K. Polymer Feed System

The polymer feed system consists of pumps and control valves that are used to control the feed of chemicals into the polymer mixing tank for the coagulation of the sludge prior to it being fed to the sludge dewatering box. The polymer feed system was installed on the floor and became submerged by the flood waters. The polymer feed system had to be replaced as mud and water got into the unit and burnt up the motor and mud plugged up the vales and feed lines. Also miscellaneous sludge lines had to be replaced as mud was sucked up into the lines and could not be blown or washed out.

There is also an electrical sprinkler pump and a vacuum air lift pump that is used to feed the polymer feed system. The sprinkler pump is used to pull treated effluent waste water out of the dechlorination chamber and the water is used to mix with the polymer chemicals. This is being used in lieu of purchasing drinking water from the public utility provider. The air lift pump is used to transport the sludge off the bottom of the clarifiers to the polymer mixing tank for treatment prior to going into the dewatering sludge box. Both pumps were submerged and had to be replaced as the motor was burnt up on the sprinkler pump and mud and debris was sucked up into the air lift pump causing it to be come inoperative.

L. Sludge Dewatering Box

The existing concrete pad for the sludge dewatering box was damaged due to flood waters running under the existing concrete pad and thus damaged the pad and causing parts of the pad to break in half. A new concrete pad and containment curb had to be constructed. When the sludge is pumped into the dewatering box the excess water drains out the bottom of the tank and onto the concrete pad. This water then flow into a floor drain and the water drains back into the influent wet well for processing through the plant. The concrete pad has to be water tight as there permit does not allow for this water to flow off site.

In order for the plant to get back into operation as soon as possible a new dewatering box was purchased. The new box will dewater the sludge in 24 hours as opposed to the existing dewatering box that took 10 days to dewater the sludge. This increase in time allowed Lynwood Utility Corporation to pump out the basins and clarifiers and dispose of the sludge at a permitted landfill once a day, which in turn the plant was able to get back on line in a timely manner to meet the current NPDES discharge permit.

M. Standby Generator

The treatment plant has a 200kw Kohler diesel generator with an automatic transfer switch that will supply electrical power to the plant in case of an electrical outage. The generator is located outside on the main building and is mounted above the existing grade on a concrete pad. The generator was partially submerged by the flood water causing damage to the wiring. Also water got into the motor and a portion of the motor will have to be taken apart and cleaned prior to making the generator operational. At this time it has not been determined the total damage done to the motor and electrical generator system.

Mr. Tyler Ring, President Lynwood Utility Corporation June 17, 2010 Page 6 of 7

N. Electrical/Mechanical/Laboratory Building

The main building that controls all the operation of the plant was flooded with approximately 10-12 inches of water entering the building. Due to the high velocity of the water and the debris that was in the flood waters hammering against the building, damage was done to the block walls and concrete floors. The following are the items that were noted to be damaged to the structure itself.

- At the left rear corner cracking and separation of the mortar joints were noted. The cracks were approximately 1/4" to 1/2" wide and stair stepped down running from the ceiling to the floor following the mortar joints. The floor slab has sunk and separated from the wall which tends to lead to the possibility that the wall has rotated outward.
- At the left front corner cracking and separation of the mortar joints were noted. The cracks were approximately 1/4" wide and stair stepped down from the ceiling to the floor following the mortar joints. The floor slab has sunk and separated from the wall which tends to lead to the possibility that the wall has rotated outward.
- The floor slab has broken and the wall has pulled away from the floor slab where the main electrical conduits enter the building.
- The floor slab running along the left hand wall has separated from the block wall and there is a 1/2" to 1" gap between the wall and the concrete floor slab.
- At the right rear corner cracking and separation of the mortar joints were noted. The cracks were approximately 1/4" to 1/2" wide and stair stepped down running from the ceiling to the floor following the mortar joints and splitting some blocks.
- At the right front corner cracking and separation of the mortar joints were noted. The cracks were less than 1/8" wide and stair stepped down running from the ceiling to the top of the double door frame.

In order to correct the above problems and to prevent them from becoming greater problems in the future the buildings foundation and footers should be stabilized by installing a series of piers/pilings around the exterior footer. The footer should be exposed so the piers/pilings can be attached to the footer. The piers/pilings should be hydraulically sunk to either rock or stable bearing pressure. Once the building has been stabilized then the mortar joints should be tucked and the portion of the concrete floor that has sunk and separated from the walls removed and a new floor slab installed.

This building also contains rooms for the storage of the chlorine cylinders and sodium dioxide cylinders. These chemicals are used for the disinfection of the waste water and to remove the chlorine residual from the waste water prior to entering the Harpeth River. Due to the back pressure in the discharge lines mud was sucked up into the chlorine and sodium dioxide flow regulators. Both flow regulators had to be removed and cleaned. Since the flow regulators have small operating valves and are very sensitive to debris they should be replaced to ensure that the correct amount of chemical is being supplied to the waste water effluent. If too much or not enough chemicals are being discharged then you could possibly have problems meeting the current discharge permit, which could lead to fines from the Tennessee Department of Environment and Conservation. Also it was noted that mud has gotten into both scales causing them to not work property. The scales need to be working correcting so the plant operator can monitor when to switch out cylinders. If the scales are not reading correctly then they could still be showing that chemical is still in the cylinders, when in fact they could be empty. As with the

Mr. Tyler Ring, President Lynwood Utility Corporation June 17, 2010 Page 7 of 7

regulators this could cause possible problems meeting the NPDES permit. It was noted that the roof had been damaged with watering leaking into the sodium dioxide room. The roof needs to be repaired to prevent water entering from entering the room and getting onto the equipment that is in the room causing more damage. This building also contains the influent/effluent sampling equipment. The samplers automatically collect waste water samples of the raw sewage coming into the treatment plant and of the treated waste water leaving the treatment plant. Due to the back pressure in the discharge lines mud was sucked up into both the samplers. Both samplers had to be removed and cleaned.

Conclusion


As mentioned in the report a lot of the equipment, controls and piping were submerged in mud and debris. Some equipment was reworked to get them operating so the sewage treatment plant could be put back on line while others it was more cost efficient to replace them with new equipment. A lot of the equipment could not be cleaned and dried out completely which will lead to possible corrosion and deterioration to parts and electrical connections which will cause future operating problems. This damage will shorten the life expectancy of the equipment thus making Lynwood Utility Corporation incur future expenses to replace the damaged equipment prior to there life expectancy. These future costs will have to be passed on to the sewer customers so flood damaged equipment can be replaced and to keep the plant operating as designed. Unless each piece of equipment was totally disassembled cleaned properly and reassembled would Lynwood Utility Corporation know what type of long term damaged was caused by the flooding.


Due the flooding of the plant the Lynwood Utility Corporation suffered a great monetary cost to replace existing equipment, clean out existing treatment basins, repair damaged equipment and electrical controls and chemical feed systems. Since Lynwood Utility Corporation is a sewage system provider they are governed by the State of Tennessee, Department of Environment and Conservation, Division of Water Pollution Control and as such are bound by certain rules and regulations that they must adhere to. They operate under a National Pollutant Discharge Elimination System permit (NPDES) which states what pollutants that they must test and treat for and what discharge levels that these pollutants must be prior to discharging into a stream of the United States. In order for the sewage treatment plant to meet the permitted discharge levels all pumps, basins, structures, equipment, piping and operating controls must be working properly and be in good working order. The Lynwood Utility Corporation had no choice but to make all the necessary repairs as quickly as possible so as to eliminate possible fines from the State and to prevent dangerous and harmful bacteria being discharged into the Harpeth River, which could possibly harm humans or animals that may come into contact with untreated waste water. Therefore Lynwood Utility Corporation took the only appropriate and responsible actions that were available to them which was to replace or repair all damaged equipment and structures as quickly as possible so the sewage treatment plant could get back on line and produce a quality effluent that meets there current operating WPDEG permit.


Sincerely,

G.A.M. Engineering, Inc


Gregg M. Clingerman, P.E.









.








Tennessee Flooding TDEC/EPA Damage Assessment Report Wastewater Treatment and Collection Systems

Facility Information:	X_WWTP _	Pump Station	Date: 5/11/10
Permittee/System:_	Lynwood Utility	Corp. STP	alannas kaaluniine voor eisinis elise farradaisus kailiisiläisin kiirin kiirin kiirin kiirin kiirin kailiin ka
County: William	nson		
Permit No:TN0	029718		
City/Authority Contacts: Name and Numbers	Tyler Ring 615	5-305-1033	
EPA/TDEC Assessment In	idividuals: Humb	erto Guzman	
Damage Summary:			
Completely Offline	Damaged	X_Slightly D	amaged
General Conditions: (inclucondition as well as treatme			cal/physical and electrical
The private water treatment began to operate on 5/3/10 b It is uncertain if the facility: FEMA for financial assistant insurance company will only coordinates are Club House W -86.91117.	y 1:00 p.m. The sis meeting all of the ce for emergency repay for damage to	ystem has 4 pump : eir permit limits. The esponse costs. The o the office/lab buil	stations and all are operating he facility has applied to e facility owner stated that th ding. The correct address ar
Infrastructure Assessment	:		
Long Term Needs: None			
Short Term Needs: <u>None</u>	5 .		
Immediate Assistance: None	2		



The Lynwood Utility Corp. STP. The office/lab is in the background.

11 Day Later - See picturer @ Time of Flood

Α.

BRENNTAG			er e	\$3 582 90		E		00 000
BRENTWOOD RENTAL & SALES				\$1.317.80		\$764 OO	70 177 04	93,382.90
			0.00	0		6/01.23	40,417.01	\$5,486.34
			\$838.48					\$838.49
LOVE				\$355.41				\$355 41
HOME DEPOT				\$1.836.45				\$1 83E 1E
LOWES				\$448 35				\$ 1,000.40
O I V II V				00.0				\$448.35
INIEALO					\$680.70		-	\$680.70
NAPA AUTO PARTS		-		\$759.43				\$750 A3
NASHVILLE TRACTOR & EQUIPMENT		8359 21						7
	0 1 0 0 0							\$358.21
STATE SOLONIAL PERS	\$2,179.50							\$2,179.50
RESEARCH SOLVENTS & CHEMICALS				\$1.407.90				\$1,407,00
SUPPLIES		Harris and the second s		\$8 030 35				00. 70t. 0
		-		00,404,00				\$8,232.35
VVELDING ONLIMITED				\$552.21				\$552.21
	\$2,179.50	\$359.21	\$838.49	\$18,492.80	\$680.70	\$761.23	\$3,417.31	
			THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER,	The state of the s				

\$26,729.24

FLOOD EXPENSE REPORT

BRENNTAG

DESCRIPTION	UNITS	TOTAL QNTY	UNIT PRICE	TOTAL	
5/5/2010 1501b CYL SULFUR DIOXIDE	9	006	0.53	\$477.00	
501b BAG ALUMINUM SULFATE STNRD GRANULAR	42	2100	0.5692	\$1,195.32	
1501b CYL LIQUID CHLORINE	8	1200	\$0.86	\$1,033.08	
				\$2,705.40	
		CON	CONTAINER DEPOSIT	\$800.00	
		FU	FUEL SURCHARGE	\$52.50	
	ithem websis	NSURANCE & S	INSURANCE & SEC SURCHARGE	\$25.00	
			L	\$3,582.90	

FLOOD EXPENSE REPORT LYNWOOD UTILITY CORP

BRENTWOOD RENTAL & SALES

The set A to	\$200.76	\$1,879,00	\$169.95	\$11.99	\$111.93	\$1,249.00	\$99.99	311.99	\$153.98	\$239.98	\$18.99	\$154.00	\$69.98	\$99.99	\$12.50	\$15.00	\$250.30	\$28.00	\$3.99	\$53.99	87.49	\$35.20	\$20.66	\$27.50	\$14.40	\$19.96	\$21.98	\$27.99	\$10.99	\$5,021.48	\$474.86	\$5,496.34
HOUNDMENN		1,879.00				1,249.00				And the second s							Transport production of the second se		And the second s	And the state of t	And the state of t	Andreas de la company de l										
Salliddus			169.95	11.99	15.99		99.99	11.99	76.99	119.99	18.99		34.99	66.66	1.25	0.30							20.66		14.40	9.98	10.99	27.99	10.99			
RENTAL	200.76											154.00		^			250.30	14.00	3.99	53.99	7.49	35.20		27.50								
REPAIRS			e de la companya de l		ecoloriste este in mile est consert es transcribit establication est planter establishment establishment estab							A CONTRACTOR CONTRACTO											THE PARTY OF THE P	er e	e main e est, i est de est a comment de l'est est de la social de l'est de l'est de l'est de l'est de l'est de	der der stellt in der de termen maan gelegenisten op ontwert op de termen op ontwert op ontwert op ontwert op	The state of the s		erikinen jarakan da siste a asenda sejarah anda sa			
VINO					_				2	2			2		10	50	1	2		-					1	2						
DESCRIPTION A WATED TDACH DIME 6 1000F DATE	A" MATER TRACE RUNG A LOCE RN L	Z Z	IN ANE AUSE	STATE OF THE STATE	3" WATED TOACH BLAND & LOCAL	A VIA I RANGE FOR A HOSE	S" CTDAINED	AND INCIDENT TO THE PROPERTY OF THE PROPERTY O	3 X 30 BLUE DISCHARGE HOSE	FEMALE DINOK COMMENT	MANITOLE 42000FRS DI OMITO	1 A" V FOLD LIE DISOLANDELLE	ייי ליהי דומקדו וואספר הכטר כיי	DODLING OF THE PROPERTY OF THE	SPT30 SUNSCREEN WIPES	PULITRU ROPE 5/16" PER FT	A TO CHM COMPRESSOR	3/4 X 50 HOSE W/CROWS FOOT	5/4 CROWS FUCI FINE	STEINE CARBIDE BIL 3/4" X 11"	10 FLED OCHOPHET STEEL FEEL	STABLED BORE NO F 120 SET	10' FI ED CONOBETT VIDEATOR	DOZ BITETATEV CLOVES	DOZ BEOLEMIEDSEV OLOVES	A/8" V FO! HOSEDIAL	9	MAN E BITTON LAND IN ANATON	WALL DO LOW DANDLE ADAP LEK			
5/3/2010	21220							No. of the state o	+	The state of the s	5/3/2010	2122	5/6/2010	200		5/7/2040	2/3//2		5/12/2010	0102120	5/13/2010	01.02/01/0	5/18/2010					-	-			

FLOOD EXPENSE REPORT

DATE DESCRIPTION	SALLONS.					
5/3/2010 HOME DEPOT FUEL CNTR	2 141				CAR WASH	TOTAL
5/3/2010 HOME DEPOT FILE CNTD	14.7	7.848	6.10			\$6.10
M	26.111	2.929	76.48			0, 0, 0
S/S/ZUTU MAPCO MART	33.602	\$2.88	NF 30			\$/0.48
5/4/2010 KIRBY'S BP	20315	00.00	30.74			\$96.74
5/4/2010 MILES AUTO SPA	200	90.07	89.97			\$89.97
5/4/2010 KIRBY'S BP - WATER					\$11.00	\$11.00
5/4/2010 VIOUN DE DE			0.00	\$17.22		\$47.00
STATE OF THE PROPERTY OF THE P	15.052	83 14	30.74			77.//6
5/4/2010 KIRBY'S BP	75077	0000	C7.1+			\$47.25
5/6/2010 HOME DEPOT ELIEL CALE	17.01	43.07	46.89			\$46.89
	26.781	\$2.93	78.44			0.00
5/6/2010 SHELL - WATER & ICE						\$78.44
5/8/2010 HOME DEPOT FUEL CNTR				\$9.77		\$9.77
5/11/2010 HOME DEBOT CLIFF ONTE	07	\$2.83	56.58	******		ቀገብ ጉል
THE DELOCATION OF THE PROPERTY	21.612	\$2.93	63.30			00.00
5/14/2010 HOME DEPOT FUEL CNTR	29 05	60.00				\$63.30
5/15/2010 SHFI	00.01	94.83	85.09			\$85.09
Z/47/04001-04-04-04-04-04-04-04-04-04-04-04-04-04-	21.228	\$2.87	60.90			0000
SITIZATU HOME DEPOT FUEL CNTR	30.869	\$2.93	90.42			900.90
		-		The state of the s		\$90.42

\$836.14 \$2.35 \$838.49

FLOOD EXPENSE REPORT

WISHER BOOTS 5 \$16.25 PAPER TOWELS 1 \$18.05 PAPER TOWELS 1 \$18.05 PAPER TOWELS 2 \$2.05 PAPER TOWERS 2 PAPER TOWERS	DATE	DESCRIPTION	VILVO	REPAIRS FUEL SU	SUPPLIES MEALS	NOTAL
R TOWELS 1 \$9.98 Y TOWELS 2 \$7.86 Y TOWELS 2 \$32.25 XTENSION CORD 1 \$15.99 BROOM 2 \$5.89 D HANDLES FOR BROOMS 2 \$6.89 EGE 2 \$6.89 TAP 1 \$15.45 TAP 4 \$4.97 TER 4 \$4.97 TOKEDL 4 \$4.97 H BAGS 2 \$4.97 CICACEDL 4 \$1.548 MASK 1 \$4.97 GLOVES 1 \$4.97 BROOM 2 \$1.548 BROOM 2 \$1.56 SSUMP PUMP 1 \$3.97 AL COUPLING \$4.37 AASE \$3.97 AANIZED BRUSH 1 \$6.46 AMIZED BRUSH 1 \$6.46 TOWELING \$6.46 \$6.46	5/3/2010	RUBBER BOOTS	5	**		\$81.25
Y TOWELS 2 \$7.86 Y TOWELS 2 \$7.86 XTENSION CORD 1 \$12.00 BROOM 2 \$15.99 BROOM 2 \$6.89 LEGE 2 \$6.89 LEGE 2 \$6.89 TAP 1 \$15.45 TAP 4 \$4.97 TER 4 \$4.97 TAP \$1.64.5 \$1.96 TER 4 \$1.96 TAP \$1.06 \$1.96 TAP \$1.96 \$1.96 MASK \$1.96 \$1.96 GLOVES \$1.96 \$1.96 BROOM \$2 \$1.96 SSUMP PUMP \$1 \$1.06 ASE \$1.37 ANE \$1.37 ANE		PAPER TOWELS	_		\$9.98	\$9.98
XTENSION CORD 2 SXTENSION CORD 1 SXTENSION CORD 4 BROOM 2 BROOM 2 SEGE \$5.96 FEGE \$6.89 TAP 1 TAP 1 TAP 4 NITRIL 4 NITRIL 4 SA 97 NITRIL 4 H BAGS \$4.97 MASK 1 GLOVES \$15.48 BROOM 2 ANASK 1 GLOVES \$1.58 BROOM \$1.58 AL COUPLING 1 AL COUPLING 1 ANIZED BRUSH 1 S6.46 1 S6.46 1 S6.46		TERRY TOWELS	2		\$7.86	\$15.70
XTENSION CORD 1 \$112.00 BROOM 2 \$15.99 BROOM 2 \$5.89 EGE \$5.89 TAP 1 \$15.45 TAP 1 \$15.45 TAP 1 \$15.45 TAP 4 \$15.45 NINTRIL 4 \$4.97 NINTRIL 4 \$4.97 NINTRIL 4 \$4.97 HAGGS 2 \$15.48 GLOVES 1 \$4.49 BROOM 2 \$4.49 GLOVES 1 \$1.58 SUMP PUMP 1 \$105.00 AAE 1 \$105.00 AASE 1 \$1.30 AANIZED BRUSH 1 \$6.46 TANIZED BRUSH 1 \$6.46		50' EXTENSION CORD	2	67	832.25	\$64.50
BROOM 4 \$15.99 D HANDLES FOR BROOMS 2 \$5.89 EEGE \$5.89 \$5.89 TAP 1 \$15.45 TAP 1 \$4.97 TAP 1 \$4.97 TAP 4 \$4.97 TER 1 \$4.97 NINTRIL 4 \$4.97 CREDL 4 \$4.97 H BAGS 2 \$1.98 GLOVES 1 \$4.49 BROOM 2 \$4.49 E \$1.98 \$1.80 SUMP PUMP 1 \$1.05.00 AL COUPLING 1 \$1.05.00 ANSE 1 \$3.97 ANIZED BRUSH 1 \$6.46 1 \$6.46 1 56.46 1 \$6.46		100' EXTENSION CORD	1	· •	112.00	\$112.00
2 \$37.99 DOMS 2 \$5.89 \$5.89 1 \$15.45 1 \$4.97 2 \$4.97 2 \$15.48 1 \$9.88 2 \$4.49 1 \$1.58 1 \$1.58 1 \$1.50 1 \$1.50 1 \$3.97 1 \$3.39 1 \$5.39 1 \$5.45 1 \$5.45		MOP	4	0	315.99	\$63.06
DOMS 2 \$5.89 2 \$5.98 1 \$15.45 1 \$4.97 2 \$1.98 1 \$1.98 1 \$1.98 2 \$1.98 2 \$4.49 2 \$4.49 1 \$1.58 1 \$105.00 1 \$3.97 1 \$3.97 1 \$5.98 1 \$5.98 1 \$5.98 1 \$5.98 1 \$5.98 1 \$5.99 1 \$5.99 1 \$5.96 1 \$5.96 2 \$5.46		PUSH BROOM	2	0	37 00	\$7£ 00
2 \$5.98 1 \$15.45 1 \$9.97 4 \$4.97 2 \$15.48 1 \$1.98 1 \$1.98 1 \$1.98 1 \$1.98 1 \$1.98 1 \$1.58 1 \$1.05.00 1 \$1.05.0		WOOD HANDLES FOR BROOMS	2		\$5.80	644 70
TAP TAP FR 1 \$15.45 ER 1 \$29.7 ITRIL 4 \$4.97 PREDL 4 \$4.97 ITRIL \$4.97 \$4.97 I BAGS \$15.48 \$1.98 NASK 1 \$1.98 SLOVES \$4.49 \$1.00 SLOWP PUMP 1 \$10.500 ASE 1 \$10.500 ASE 1 \$1.37 NIZED BRUSH 1 \$6.46 I \$6.46 \$6.46 \$6.46		SQUEEGE	2		\$5.00 \$7.08	944.06
ER 1 \$9.97 IITRIL 1 \$9.97 SITEDL 4 \$4.97 IBAGS 2 \$1.548 MASK 1 \$9.88 SLOVES 1 \$9.88 SLOVES 1 \$1.58 SLOWP PUMP 1 \$1.56.00 ASE 1 \$4.49 L COUPLING 1 \$4.37 ANIZED BRUSH 1 \$6.46		2' TRI TAP	-	8	\$14 AE	945 45
IITRIL 1 \$4.97 SREDL 4 \$4.97 I BAGS 2 \$15.48 SILOVES 1 \$1.98 SLOVES 1 \$9.88 SLOVES 1 \$4.49 SLOWP PUMP 1 \$15.88 SUMP PUMP 1 \$15.05.00 ASE 1 \$4.37 I COUPLING 1 \$6.46 ANIZED BRUSH 1 \$6.46		ADAPTER	1	7	00.00	\$10.40
SREDL 4 \$4.97 I BAGS 2 \$4.97 I BAGS 4.97 I BAGS 5.15.48 WASK 1 \$1.98 SLOVES 1 \$9.88 SLOVES 1 \$4.49 SLOWP PUMP 1 \$105.00 ASE 1 \$3.97 I COUPLING 1 \$56.46	-	GM40NITRII			÷ 0.00	48.87
NASK \$4.97 1 BAGS \$15.48 NASK 1 \$1.98 \$1.98 \$1.0VES 1 \$1.0VES \$9.88 BROOM \$4.49 \$1.0VES \$1.98 \$1.0VES \$1.98 \$1.0VES \$1.00 \$2 \$1.00 \$4.49 \$1.00 \$4.49 \$1.00 \$4.49 \$1.00 \$4.5E \$1.00 \$3.97 \$1.00 \$4.37 \$1.00 \$1 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$2.00 \$3.98 \$3.98 \$1.00 \$4.00 \$1.00 \$4.00 \$1.00 \$4.00 \$1.00 \$4.00 \$1.00 \$4.00 \$1.00 \$4.00 \$1.00 \$4.00 \$1.00 \$5.00 \$1.00 \$6.40 \$1.00 \$6.40 \$1.00 \$6.40 \$1.00 \$6.40 \$1.00 \$6.40 \$1.00 \$6.40 \$1.00 \$6.40 \$1.00 \$6.40 \$1.00 \$6.40					44.87	\$4.97
BAGS \$15.48 MASK \$1.98 SLOVES \$1.98 BLOVES \$1.98 SLOVES \$1.98 BROOM \$4.49 SUMP PUMP 1 \$15.88 ASE \$3.97 \$4.37 L COUPLING \$4.37 \$3.98 ANIZED BRUSH 1 \$6.46 ASE \$3.98 \$6.46	***************************************	GNIPVCREDL	4		\$4.97	\$19.88
MASK 1 \$1.98 SLOVES \$9.88 SLOVES \$4.9 BROOM \$4.49 SUMP PUMP 1 \$15.88 SUMP PUMP 1 \$105.00 ASE \$3.97 \$4.37 L COUPLING 1 \$4.37 ANIZED BRUSH 1 \$6.46	**************************************	I KASH BAGS	2	63	\$15.48	\$30.96
SLOVES \$9.88 BROOM \$4.49 1 \$15.88 SUMP PUMP 1 \$105.00 ASE \$3.97 L COUPLING 1 \$4.37 ANIZED BRUSH 1 \$6.46		DUST MASK	Ψ-		\$1,98	\$198
BROOM 2 \$4.49 SUMP PUMP 1 \$15.88 SUMP PUMP 1 \$105.00 ASE 1 \$3.97 L COUPLING 1 \$4.37 ANIZED BRUSH 1 \$3.98 ANIZED BRUSH 1 \$6.46		10PR GLOVES	-		\$9.88	88 88
SUMP PUMP 1 \$15.88 ASE L COUPLING 1 \$3.97 ANIZED BRUSH 1 \$6.46		WISK BROOM	2		\$4.49	\$8.08
SUMP PUMP 1 \$105.00 CASE 1 \$3.97 AL COUPLING 1 \$4.37 ANIZED BRUSH 1 \$5.46	Annual Art Market Street S	HOSE	-	5	\$15.88	\$15.30
AL COUPLING AL COUPLING 1 \$4.37 ANIZED BRUSH 1 \$3.98		1/3HP SUMP PUMP	_	45	105 00	\$105.00
AL COUPLING ANIZED BRUSH 1 \$3.98 1 \$6.46		NPL CASE	_		\$3.97	43.07
ANIZED BRUSH 1 \$3.98 1 \$6.46 1		1.5 GAL COUPLING	-		25 73	64.37
\$5.46		GALVANIZED BRUSH	-			64.07
\$6.46			_ ,		\$3.98	\$3.98
\$63.66		0100			\$6.46	\$6.46
\$752.52						\$638.86
\$752.52					_	\$63.66
						\$752.52

FLOOD EXPENSE REPORT

100' EXTENSION CORD		\$112.00	\$112.00
FG3PKPIGGL		\$9.88	\$9.88
40W48T12CW	3	\$3.97	\$11.91
WEDGE ANCHOR	8	\$1,44	\$11.52
3/8 x 6 BIT	2	\$3.67	\$7.34
BOSCH BIT	2	\$6.79	\$13.58
1/3HP SUMP PUMP		\$105.00	\$105.00
PVC40 PIPE		\$1.81	\$1.81
PVC40 PIPE	9	\$3.75	\$22.50
CMT HANDIPAK		\$6.96	\$6.9\$
3/4 ADAPTER	4	\$0.44	\$1.76
3/4 × 4 GALNIPL	4-	\$1.59	\$1.59
3/4 FPBVLWSTH	-	\$12.99	\$12.99
3/4 x 4.5 GNPL		\$1.65	\$1.65
SAL45DELB		\$2.09	\$2.09
3/4/2 BUSHIN	_	\$1.40	\$1.40
PVC ADAPTER	7	\$0.54	\$0.54
PVC BUSHING	2	\$0.97	\$1.94
1 1/4 COUPLING	7	\$0.55	\$3.85
3/4 PVC EL45	-	\$0.64	\$0.64
1/2 x 260 TAPE	1	\$0.98	\$0.98
GMCUFFNEOX		\$3.97	\$3.97
4WAYCOATLG	_	\$5.99	\$5.99
HOMER BUCKET		\$2.34	\$7.02
O BATTERIES (12PK)	е	11.69	\$35.07
			\$383.98
			\$35.52

FLOOD EXPENSE REPORT

H COMPANY OF THE COMP

DATE	DESCRIPTION	ONTY REPAIRS	FUEL SUPPLIES	MEALS TOTAL
5/5/2010	5/5/2010 GM50DVINYL	2		
	GMCUFFNEOL	13	\$3.97	#5.34 #5.4 64
	12' LADDER		\$254 00	\$25A OO
	3/8 2x4 BC	2	\$8.14	\$16.00
	3/8 x 1.5 HBLT	4	\$0.24	35.01
	3/8 HEX NUTS	4	1108	# C C C C C C C C C C C C C C C C C C C
	3/8 CUTWSHR	4		40.44 40.40
	LOCKWASHERS	4	\$0.18	\$0.02 \$0.72
5/6/2010	SLEEVE ANCHOR	5	\$0.07	27.00 20.00
	1/2 BO BIT		\$10.47	64.05 74.07
	SHARPIE MARKER		80.07	10.00 0.00 0.00 0.00
	60" TPHND 11/8	2	0.00	18.00
	SCRFWS	7	9109	\$12.98
-			/A.44	54.9
and the state of t	SQUEEGEE	2	\$17.96	\$35.92
				\$404.63
				\$37.43
				\$442.06
				The same of the sa

FLOOD EXPENSE REPORT

THE HOME DEPOT

	I © ITAL	\$6.76	\$2.99	& R RO	60.00	3/./6	\$7.66	\$7.98	1000	18.844	\$9.32	0000	\$12.88	47 97	20.19	\$14.85	\$29.85	\$39.86	\$203.54	\$18.83	\$222.37	
	Surallian Mirallo	4 3.38	\$2.99	\$5.69	\$0.07	-0.00	\$3.83	\$5.58	\$40.07	0.01	\$4.66	AG 77	**.O*	20.24	\$2.07	⊕4.3 /	\$5.97	\$39.86				
THE SEVERS A					80	2	7				7	2	A STATE OF THE PERSON NAMED IN THE PERSON NAME		5		ವಿ	-				
DESCRIPTION		TIM NO.	H-1		ANCHOR		<u>T</u>	114	224			ndermelet			ZZ/E	ARASS HOFF OF C		JW PULL				
DATE	5/8/2010 2X60YDAPDCTP	TIA MSM 8X91/2		וום עספסם	SLEEVE ANCHOR	16oz GRSTF	5/11/2010 AP 7.25.24T	NA 10000	לא ומטוא	5/13/2010 2x4 12HT	H-107 F-10	H01 4X7	5/15/2010 POWI CK TAPE		5/24/2010 SWP NOZZLE	RRASSH		Z ION POW PULL				

LYNNOOD UTELTY CORP

FLOOD EXPENSE REPORT

DATE	DESCRIPTION	ONTY REPAIRS FI	FUEL SUPPLIES N	MEALS TOTAL
5/4/2010	6CT PAPER TOWELS	V	\$11.97	
And the Principle of th	SOFT PVC GLOVE W/ GAUNT	3	\$6.98	\$20.94
5/5/2010	GRAIN LEATHER W/ BALL		\$9.98	\$0.0%
	TRUE TEMPER FORGED CULTIV	2	\$34.96	460 02
	TRUE TEMPER FORGED CULTIV	8	\$14.98	\$44.04 \$44.04
	200CT SHOP TOWELS	4	\$0.0%	#5.4#÷
	12PK TERRY TOWELS	2	80 98	\$43.30 \$43.06
	24PK SHOP TOWELS	2	\$6.08	00.00
	200CT SELLARS GREENX TOWELS		\$0.00 \$0.40	09.01.60
5/17/2010		2	\$11.07	04.90 VO 000
	3PK BROWN JERSEY GLOVE	8	42.08	\$20.04 \$0000
	50LB SAKRETE FAST SET	2	80 P%	\$42.04 \$0.08
	SQUARE POINT SHOVEL	2	\$12.08	\$3.30 \$7.50 \$7.50
	4x4x8 ACQ TOP CHOICE	-	85.07	\$20.80 \$5.07
	12oz GLOSS WHITE STOPS	2	(C.C.)	90.39
	1.5" HC FENCE STAPLE		43.7%	00.40
	60z GEL SCENTS	4	84 08	47.00
	18" ALUM PIPE WRENCH	2	\$27.98	\$1,32 \$6.50
5/24/2010	2' ALUM STEP LADDER		835.00	455.30 455.00
demand and a spire of the second control of	9.802 SILICON WINDOW CLEANER		\$4.99	\$4.99
			and with the second second second for second se	\$410.39
				\$37.86
				\$4.8.35

FLOOD EXPENSE REPORT

MEALS

DATE	DESCRIPTION	REPAIRS FILE SHEELING	
5/3/2010	LA HACIENDA MEXICAN	SOFFILES	TOTAL
5/3/2010	PUBLIX - DRINKS, SNACKS, FOOD	53.76	\$53.76
5/3/2010		104.12	\$104,12
5/4/2010	ROYAL THAI	15.98	\$15.98
5/4/2010	LOGANS	20.35	\$20.35
5/4/2010	LOGANS	38.19	\$38.19
5/4/2010	NASHVII I E DIZZA COMBANIX	30.63	\$30.63
5/5/2010	PIBLIX - DRINKS SNACKO COOL	61.41	\$61.41
5/8/2010	PIBLIX DEINING CHACKS, FOOD	175.52	\$175.52
(40/0040	A TYXY DAILY GINACKS, TOOU	18.73	\$18 73
10/2010	STINZULU J ALEXANDERS	200	0000
5/12/2010	COZYMELS	40.03	\$46.83
		84.47	\$84.47
			\$649.99
			\$30.71
			\$680.70

FLOOD EXPENSE REPORT

NAPA AUTO PARTS

DATE	DESCRIPTION ONLY REPAIRS		
5/3/201(が _	TOTAL
· manus and a second	SAFETY EYEWEAR	88.0c	\$101.98
5/5/2010	SIOOL	13.49	\$13.49
	7 TOTT (11 TOTT)	\$4.47	\$4.47
	א ובאן ובאן כנוף	\$4.89	\$10 KB
	BATTERY CABLE TERMINAL	&1 30	9.00
	ELECTRIC FUEL PUMP KIT	07.07	\$8.34
***************************************		948.40	\$48.49
	Ω	\$18.99	\$37.98
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	\$26.49	\$26.49
And the second s	אוא דור ובא	\$39.49	478 08
	30z PTEX BLUE RTV	64.00	00.0
	SAFETY EYEWEAR	04.40	\$4.99
	TOS DIESEL FLEL CONDITIONED	\$7.99	\$7.99
	440. OTANDERSO T	\$15.29	\$15.29
	1 IOZ OTAKTING PLUIU	\$2.89	&£ 70
	ROTELLA 15W40 GAL	644.00	0 / 00
	PREM AW 32 HYD FL 5G	\$0.4.00 \$0.0	\$126.81
5/6/2010		86,854	\$79.98
	TOOL TO THE TANK THE	\$16.29	\$16.29
		\$0.98	\$9.80
	אוא רוב ובא	\$24.35	\$24.35
	8 x 10 TARP	818.00	00:14
	30qt NAPA HEAVY DUTY	00.00	\$16.00
5/18/2010	AND THE PROPERTY OF THE PROPER	\$3.08	\$37.08
		\$10.99	\$10.99
		The state of the s	

\$64.30 \$769.43

FLOOD EXPENSE REPORT

NASHVILLE TRACTOR & EQUIPMENT

DATE	DESCRIPTION	QINITY	REPAIRS FUEL SHIPPLIES	S IVEIM SE	VAIS OR
5/3/2010	5/3/2010 24D/504 FILTER	2			edo eo
	23E/504 FILTER	2	8 04		\$12.30 \$40.00
	510 FILTER	-	XC 0.24		9 0.08
And the state of t	アメントアン・コニ ナナの		410.NO		\$40.28
	310/1321 FILIEK	,	\$53.09		\$53.09
5/4/2010 MOTOR	MOTOR	7	\$167.83		0467 00
	CORE - STA				50.701.0
	SWITCH				₩ 1.00
		_	\$30.UZ		\$38.02
				The state of the s	

\$328.80 \$30.41

FLOOD EXPENSE REPORT

PROFESSIONAL FEES

1.0		\$1,300.00	8427 EC	00.70.9	\$742.00	\$0.00	\$0.00	\$2,179,50	
ð N	0.000	\$1,300.00	\$137.50	0	\$742.00				
MINO		_	-		_				
DESCRIPTION	LEGAL ADVICE		LEGAL AUVICE	FNGINEEDING EVOLUCE	בייסייירבייייט האדמיטה				
VENDOR	5/31/2010 BRANSTETTER, STRANCH & JENNINGS	5/31/2010 ORTALE KELLEY HERREDT & CDAMPCODE		O' IO/ZU IO G.A.M. ENGINEERING, INC					
DAITE	5/31/2010	5/31/2010	0400/04/0	0/10/2010					

\$2,179.50

FLOOD EXPENSE REPORT

RESEARCH SOLVENTS & CHEMICALS, INC.

-1					
	1,353.00				
					
γ					
			ender in the second or an enterprise find of the second		
	803.00	803.00	2.20	365	6/1/2010 1 G BULKGL METHANOL
	550.00	550.00	2.00	275	5/17/2010 1 G BULKGL METHANOL
	TOTAL	OHEMICALS	UNIT PRICE	ONTV	DATE DESCRIPTION

54.90

SMSI
\$20 8
100 100 100
2007
)
5

8	WASTE MANAGEMENT	DESCRIPTION ROLL-OFF DI IMPETED	> LNO		T GE	
\$	WALMART	PADD F	-	\$140,00	\$140.00	
4		DRAIN PILIG	2	\$12.96	\$25.92	
20	STAMFORD SCIENTIFIC INTERNATIONAL	9" EPDM DISC MEMBRANE		\$2.96	\$2.96	
+		CCARD PROCESSING FEE	20,	\$10.40	\$520.00	
4		SHIPPING & HANDI INC.		\$36.00	\$36.00	
왺	WALGREENS PHOTO	PICTI RES	qua.	\$199.95	\$199.95	
_		PICTURES	e	\$4.00	\$4.00	
	ON METHODS	ALLCETE 20 5 GAI DAII		\$14.63	\$14.63	
4	DICKS SPORTING GOODS	3PLYNYLON COLL OIL	4	\$45.50	\$182.00	
4		3PLYNYLON		\$99,99	\$99.99	
4		RUBBER HID B/B		\$99.99	\$99,99	
4		RIBBER HID B/D	-	\$27.99	\$27.99	
₹	ACADEMY SPORTS	RANTAM WATER BOOTS	-	\$27.99	\$27.99	
_		BANTAM MATER BOOTS		\$39.99	\$39.99	
익	OFFICE DEPOT	16GB MEMORY CARD	*	\$39.99	\$39.99	
ळ	SPECTRUM EQUIPMENT PARTNERS, LTD	30YD FILTER SCREEN	-	\$34.99	\$34.99	
_		30VD TIPRO DUASE SERVICES	4	\$195.00	\$780.00	
\downarrow		SHIPPING & HANDING	22	\$60.00	\$1,320,00	
_		30YD FII TER SCREEN	4	\$800.00	\$800.00	
	Charles and the contract of th	SHIPPING & HANDLING	9	\$195.00	\$1,170,00	
<u>≩</u> [:		PICTURES	-	\$118.00	\$118.00	
4	A-WELDERS & MEDICAL SUPPLY INC.	MILER RHSOSTAT		\$42.46	\$42.46	
	And the second s	MILERCAP		\$87.00	\$87.00	
	DISCOUNT PLUMBING	4" PVC	-	\$8.83	\$8.83	
		4" PVC. NOWN TIES	20	\$1.80	\$36.00	
		4" PVC S.40 DIDE	7	\$8.39	\$58.73	
		4 FENNCO	10	\$1.80	\$18.00	
		4 PVC DOWN CAP	3	\$6.50	\$19.50	
		PINTRIFFGEE	4	\$2.71	\$10.84	
_[:	Advidation acceptation designates and participates	4 PVC S-40 CAP		\$7.96	\$7.96	
	HARPETH VALLEY TRUE VALUE	ROLTS NITE SCEENIS	1	\$4.75	\$4.75	
	- Andreas Commission and Angel	ROLTS NITE SCHOOL	4	\$3.29	\$13.16	
		BOLTS MITS SOBEMS	ω	\$0.40	\$3.20	
		EVERROY ADV CALL BATTERS	80	\$5.59	\$44.72	
5	(American de servicio de la compansión d	COMPLITED SOFT WAR	•	\$7.02	\$7.04	
\mathbf{z}	In	DESIGNATION PRINCE	₹	\$239.99	\$239.99	
3		CHAPT DANIEL MOLCALING UNIERTED	-	\$42.00	00 CP3	
8	WASTE MANAGEMENT	ROIL OFF DIMETER	2	\$24.00	\$48.00	
**************************************	A CONTRACTOR OF THE PROPERTY O	DISPOSAL CEES	7	\$397.60	\$397.60	
	The Commence of the Commence o		-	\$1,338.17	\$1.338.17	
				The second of th		

FLOOD EXPENSE REPORT

WELDING UNLIMITED, INC.

DATE	DESCRIPTION	GNITY F	REPAIRS FUEL SUPPLIES N	MEALS TOTAL	gegrinalismo -
5/4/2010	5/4/2010 STEEL sq ft. 063 ALUM BRITE TREAD	16	\$7.00	\$112.00	
PROPERTY AND THE PROPER	STEEL sq ft .250 ALUM PLATE	416	\$0.46	\$192.00	
	LABOR	-	\$15.00	\$15.00	
5/17/2010	5/17/2010 WELDING 1/8 RODS	10	\$2.15	\$21.50	
	AUTO DARDENING HELMET	7	\$89.95	\$89.95	·
	RECOND, ACETY REG		\$75.00	\$75.00	
				The state of the s	

\$505.45

\$552.21



INVOICE

30740

ACCT. NO. LYNN

SOLD TO: LYNNWOOD UTILITY DISTRICT

321 BILLINGS COURT

SUITE 4

FRANKLIN. TN 37067

SHIP TO: WWTP

FRANKLIN, TN.

INVOICE		PURCHASE ORDER NO.	TERMS	SHIP VIA	FOB	SALES- PERSON	SALES
16 31		IIR RING	Net 30 Days			SE	NO.
QUANTITY CROERED	QUANTITY SHIPPED		DESCRIPTION		UNIT PRICE	EYTEND	ED DDIO
	2.000 2.000 2.000 2.000 2.000 2.000 2.000 2.000 2.000 2.000 2.000	PLANT BACK ON MISC. ELECTRIC	TERS AND CONTACTS TO GET LINE AFTER THE FLOOD OF SUPPLIES TERS FOR STARTERS S S PENTAL	785 MRY 2-3	126.5 82.1 1,190.2 607.1 400.0 66.0 132.0	13 9 1 2, 4 1, 0	126.53 164.38 380.42 214.28 400.00 313.50 924.00
					SALES AMOUNT	5,52	3.11
					TAXABLE TOTAL SALES TAX FREIGHT		0.00
				Thank You	TOTAL	5,52	3 11



INVOICE

30866

ACCT. NO.: LYNN

SOLD TO: LYNNWOOD UTILITY DISTRICT

321 BILLINGS COURT

SUITE 4

FRANKLIN, TN 37067

SHIP TO: RIVERLANDING P.S.

LYNWOOD U.D. FRANKLIN, TN.

INVOICE	DATE	PURCHASE ORDER NO.	TERMS	SHIP VIA	FOB	SALES- PERSON	SALES NO.
			Net 30 Days			SE	7
QUANTITY ORDERED	QUANTITY SHIPPED	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	DESCRIPTION		UNIT PRICE	EXTEND	ED PRIC
3.11	3.00	AFTER THE MAY DAMAGED FARTS. 27431-161 GR A 27321-206 GR C 27321-213 GR C UPS SHIPPING F 44163-289 GR R 46411-161 GR F LOT GR ARV REB LOT MISC ELECT MOTORS REBUILD HOA HAMD OFF A HRS OVERTIME C HRS OVERTIME A HRS ASSIST LAB HRS STANDARD L	B TUQCILE-W; BREAKER D TEDIS404001 BREAKER B THQCILLEM1 ROM GR ON ABOVE CTATING ASSEMBLY LAP VALVES UILD PARTS RICAL COMPONENTS , BAKED UTO SWITCH/CONTACTS CNTROL LABOR TANDARD LABOR SSIST LABOR GR 480P		50. 19. 361. 20. 15. 2,077. 123. 233. 1,976. 321. 21. 198. 144. 99. 66. 96. 132. 12.	85 65 20 86 90 4, 30 60 61 1, 43 43 00 00 00 00 00 00 1,	150.75 19.85 723.36 60.66 15.86 ,155.86 246.60 233.60 ,976.61 642.86 21.43 297.00 468.00 148.50 528.00 782.00 782.00
			362 mines	2 703 th 12 10 10 10 10 10 10 10 10 10 10 10 10 10	SALES AMOUNT TAXABLE TOTAL SALES TAX FREIGHT	13,	0.00 0.00 0.00
5.55			DAY TO	Thank You	TOTAL	13,	163.39



INVOICE	
30923	*****

ACCT. NO.: LYNN

SOLD TO: LYNNWOOD UTILITY DISTRICT

321 BILLINGS COURT

SUITE 4

FRANKLIN, TN 37067

SHIP TO: LYNNWOOD WWTP MAIN P.S.

INVOICE		PURCHASE ORDER NO.	TERMS	SHIP VIA	FOB	SAL	ES-	SALES
07/30/	2010		Net 30 Days	and agreed approved from particles and particles and particles are a second and a second a second and a secon	:	SE		NO.
QUANTITY ORDERED	QUANTIT SHIPPEI	TY D	DESCRIPTION		UNIT PRIC	E EX	TENDES	 9 PR:0
1.00		MENT BACK TO TO MOTORS THAT HAD STATION AND WE	D DAMAGE OF MAY 2010, CURHE SITE AND PULLED ONE OF DEEN SUBMERGED IN THE MAREWORKED THE MOTOR. THE NOT BEEN PULLED YET.	The state of the s	1,63%	• E - C - C - C - C - C - C - C - C - C -		34.52
					SALES AMOUNT		1,356.	
.00				į	TAXABLE TOTAL SALES TAX FREIGHT		ĵ.	
·				Thank You	TOTAL		î,388.	= -



INVOICE
30865

ACCT. NO.: LYNN

SOLD TO: LYNNWOOD UTILITY DISTRICT

321 BILLINGS COURT

SUITE 4

FRANKLIN, TN 37067

SHIP TO: LYNNWOOD UTILITY DISTRICT

7 X 10 STATION @ WWTP

SN 01-5988A

INVOICE	EDATE	PURCHASE ORDER NO.	TERMS	SHIP VIA	and the second	FOB	SALES- PERSON	SALES NO.
07/30,	/2010		Net 30 Days					-
QUANTITY ORDERED	QUANT	ITY ED	DESCRIPTION	1		UNIT PRICE	EXTEND	ED PRIS
1.00	9.		JABOR	BREX		1,178.87 96.13 66.33		
					SALES A	MOUNT	2,2	₹ 6 . € ⁻
0.00 0.00						TOTAL ES TAX REIGHT		
				Thank You		TOTAL	3 7 8	€.57

Scott

LYNWOOD UTILITY CORP.

SOUTHERN SALES COMPANY

9/17/2010

Inv#30740/Flood May 2010/Replaced Lots of Stuff.

5,523.11

24!

Tennessee Commerc Inv#30740

5,523.11

Scott

NWOOD UTILITY CORP.

SOUTHERN SALES COMPANY

10/15/2010

2516

Inv#30923/Pump repair after flood Inv#30865/Lot Motors Baked & Repaired

2,386.51 2,156.57

Tennessee Commerc Inv#30923, & 30865

4,543.08

SOUTHERN SALES COMPANY

9/17/2010

Inv#30740/Flood May 2010/Replaced Lots of Stuff.

5,523.11

249

Tennessee Commerc Inv#30740

5,523.11

Scott

WOOD UTILITY CORP.

SOUTHERN SALES COMPANY

10/15/2010

2516

Inv#30923/Pump repair after flood Inv#30865/Lot Motors Baked & Repaired

2,386.51 2,156.57

Tennessee Commerc Inv#30923, & 30865

4,543.08

BERRY'S CHAPEL UTILITY, INC. 321 BILLINGSLY CT, SUITE 4 FRANKLIN, TN 37067 CIENNESSEE Bank Bank 87-854-641

Court Frank Court Frank Court Frank Court Frank Court Court Frank

11/10/2010

PAY TO THE ORDER OF

SOUTHERN SALES COMPANY INC

**3,663.39

DOLLARS

SOUTHERN SALES COMPANY INC

P O BOX 40384

NASHVILLE TN 37204

ИЕМО

Lynwood Utility Inv#30866

AUTHORIZED SIGNATURE

BERRY'S CHAPEL UTILITY, INC.

SOUTHERN SALES COMPANY INC.

11/10/2010

7034

3,663.39

Balance Owing: 9500.00

CHECKING TCB

Lynwood Utility Inv#30866

3,663.39

SOUTHERN SALES COMPANY INC

12/6/2010

3,500.00

708;

Inv#30866/Partial Pay/Bal owing 6000.00

CHECKING TCB

Inv#30866/Partial Pay

3,500.00

BERRY'S CHAPEL UTILITY, INC.

SOUTHERN SALES COMPANY INC

Acct: LYNN

12/28/2010

711(

6,000.00

CHECKING - TN CO Acct: LYNN

6,000.00

TENN. CONTRACTORS, INC.

P.O. BOX 314 FRANKLIN, TN 37065-0314 Phone 615-599-0784 Fax 615-599-0797


DATE: INVOICE #

5/10/2010 1042

Bill To: Lynwood Utility Corporation 180 Cottonwood Drive Franklin, TN

DESCRIPTION		A	MOUNT
Repaired, cleaned, and adjusted float telemetry system.			3,450.00
(Cleaned and repaired entire pump station wet well (30 ft. deep), alarm system, and float system. Repair and cleaning of 35' can station (includes dry out of pumps, motor, electrical panels, sump pumping, dehumidifier, and climate control.)			0,400.00
See attached diagram			
			as de contracto de
	TOTAL	\$	3,450.00

FLOAT DIAGRAM AT PLANT WET WELL





INVOICE

THE LEADER IN ENVIRONMENTAL TESTING

2960 Foster Creighton Road Nashville, TN 37204 800-765-0980 Fax:615-726-3404

Invoice To: Lynwood Utility (11448)

Accounts Payable 321 Billingsly Court. Ste 4 Franklin, TN 37067

Invoice Number:

49010949

Remit Payment To:

Dallas, TX 75312-2314

1408119

TestAmerica Laboratories, Inc. Dept 2314 P.O. Box 122314

TestAmerica EIN: 23-2919996

For Billing Inquiries please contact:

800-765-0980

Invoice Date: 06/10/10

Project: Project Nbr: PO Number: Sludge Analysis

[none] NA

Client Contact: Scott Davis Work Order:

Terms: Net 30 Days Payment due:

07/12/10

Lab Contact Jennifer Gambill

NTE2805

Quantity	Analysis/Description	Matrix	Rush TAT	% Rush	Unit Cost	Unit Rush Cost	Extended Cost
1	Zinc Total EPA 6010B	Soil	NA	None	\$15.00	\$0.00	F
1	TKN 351.2	Soil	NA.	None	\$45.00	\$0.00	\$15.00
1	Selenium Total EPA 6010B	Soil	NA.	None	\$15.00	\$0.00	\$45.00
1	Nitrite SW846 9056	Soil	NA	None	\$20.00		\$15.00
1	Nitrate SW846 9056	Soil	NA	None	\$20.00	\$0.00	\$20.00
1	Nickel Total EPA 6010B	Soil	NA	None		\$0.00	\$20.00
1	Molybdenum Total SW 6010B	Soil	NA.	None	\$15.00 \$15.00	\$0.00	\$15.00
1	Mercury 7471 A	Soil	NA.	None	\$15.00	\$0.00	\$15.00
1	Lead Total EPA 6010B	Soil	NA	None	\$35.00	\$0.00	\$35.00
1	Copper Total EPA 6010B	Soil	NA NA		\$15.00	\$0.00	\$15.00
1	Cadmium Total EPA 6010B	Soil	NA NA	None	\$15.00	\$0.00	\$15.00
1	Arsenic Total EPA 6010B	Soil		None	\$15.00	\$0.00	\$15.00
1	Ammonia 350.1	Soil	NA	None	\$15.00	\$0.00	\$15.00
		SOII	NA	None	\$25.00	\$0.00	\$25.00
itional Iten							
1	Environmental Management Fee						\$13.25

Invoice Total:

\$278.25

Any applicable rush charges are based on the actual turn-around-time met




COOLER F



NTE2805

Cooler Received/Opened On: 5/27/2010 @ 9:51	
Walk-in Tracking number	
IR Gun ID: 9560068	
1. Temperature of rep. sample or temp blank when opened: 73. Degrees Celsius	
3. If Item #2 temperature is 0°C or less, was the representative sample or temp blank frozen?	YES NO. NA
4. Were custody seals on outside of cooler?	YES NO. NA
If yes, how many and where:	
5. Were the seals intact, signed, and dated correctly?	YESNONA
6. Were custody papers inside cooler?	YESNO NA
I certify that I opened the cooler and answered questions 1-6 (initial)	
7. Were custody seals on containers: YES (NO) and intact	YESNO.(.NA
Were these signed and dated correctly?	YESNO. NA
8. Packing mat'l used? Bubblewrap Plastic bag Peanuts Vermiculite Foam Insert Paper	Other None
9. Cooling process: Ice Ice-pack Ice (direct contact) Dry ice	Other None
10. Did all containers arrive in good condition (unbroken)?	YES. NONA
11. Were all container labels complete (#, date, signed, pres., etc)?	YES NONA
12. Did all container labels and tags agree with custody papers?	YES.).NONA
13a. Were VOA vials received?	YESNONA
b. Was there any observable headspace present in any VOA vial?	YESNONA
14. Was there a Trip Blank in this cooler? YESNONA If multiple coolers, sequence	#
certify that I unloaded the cooler and answered questions 7-14 (intial)	2
15a. On pres'd bottles, did pH test strips suggest preservation reached the correct pH level? Y	ESNO.NA
b. Did the bottle labels indicate that the correct preservatives were used	YESNONA
16. Was residual chlorine present?	ESNQNA
I certify that I checked for chlorine and pH as per SOP and answered questions 15-16 (initial)	
17. Were custody papers properly filled out (ink, signed, etc)?	ES. NONA
18. Did you sign the custody papers in the appropriate place?	ESNONA
19. Ware correct containers used to the	ESNONA
20 Mars sufficient resource of	ES)NONA
certify that I entered this project into LIMS and answered questions 17-20 (intial)	
certify that I attached a label with the unique LIMS number to each container (Intial)	
21. Were there Non-Conformance issues at login? YESNO Was a PIPE generated? YESNO.	.).

Send QC with report sunsay re-No Z TAT bisbrist 8 era) Tat House 06/11/10 23:59 ¥. Yes sinommA X Compflance Monitoring? To assist us in using the proper analytical methods, is this work being conducted for Enforcement Action? LKM **StritiM** Temperature Upon Receipt VOCs Free of Headspace? Mitrate Laboratory Comments: regulatory purposes? muinele2 Project ID: Studge Analysis Molybdanum / Zinc × Site State: TN Site Mercury / Mickel K TA Quote #: Project #: Copper / Lead X 9:51 Arsenic / Cadmium Time E X FEDEX Ogues (absorpt) 5/17/10 adons Oste Orangung Assess Phone: 816-726-0177 Toll Free: 800-765-0560 Fax: 616-728-3404 Fex No.: 615-569-0797 Method of Shipment: (Medal sgnero) Hoek Received by TestAmerica: HHO, (Red Label) ⊗) Received by: banetiil blail Composite | C | C | C | C | Neshville Division 2860 Foster Creighton Mashville, TN 37204 × 2.50 AM 5/2/4 No of Containings Shipped Address: 321 Billingsly Court, Ste 4 Chent Name/Account 8: Lynwood Unity (11448) balgmas amil City/State/Zlp: Frenkin, TN 37097 0 Telephone Mumber: 615-305-1003 Project Manager: Scott Davis / to / to Date Sampled Sampler Hame: (Print) Sampler Signature: Sample ID / Description Special instructions alinquighed by: collection by: 1



Keep your receipt!

Val #: 0691-0917-0439-5666

0170 055 4962 05/19/10 15:57 0673075

Duplicate Receipt

******	· * * *
SOLUTIONS PLUS 267660********	****
9685029 P6310Y	580.00 *
P6310Y/AMD ATHLON II 630Q/6GB	
19.99 PACK DISC	(5)
ITEM TAX 53.66	400
9533631 CH396A#B1H	29.99 *
HP DESKJET D2680 PRINTER CH39	
40.00 PACK BISC	
ITEM TAX 2.77	
9251356 2009M	149.99
2009M 20" 1600X900/1000:1/5MS	
ITEM TAX 13.88	
9779158 ASK AN AGEN	0.99
ASK AN AGENT PRODUCT ITEM TAX 0.09	
9779167 ASK A AGENT	19.00
ASK A AGENT 6 MONTH	17.00
ITEM TAX 1.76	
************	***
PACKAGE 209845***********	
8761958 CD947FN#140	21.99 *
HP 60 RETAIL COMBO PACK US	
10.00 PACK DISC	
ITEM TAX 2.03	
米拉英男子兴奋在兴场的旅行的公共大大大大大大大大大大	
SOLUTIONS PLUS 220375********	
8856865 8044912	2.99
KASPERSKY AV BOX	
ITEM TAX 0.28	57.00
	57.00 *
3 USER KASPERSKY AV 2 YR	
20.00 PACK DISC ITEM TAX 5.27	
11CF 17A 3.21	***
5688865 TEUSB2AB2.0	24.99
DYNEX 6.0' USB GOLD A/B CABLE	27.77
ITEM TAX 2.31	
7251029 RZ JOIN	0.00 N
REWARD ZONE JOIN	
SERIAL # 2708163742	
6072313 REUARD ZONE	0.00 N
RZ CERTIFICATE EMAIL	
	99.99
2YR \$400-\$599.99 CPU BTP	
GSBTP # 3451942219	
SKU # 9685029	
EXP DATE 05/19/2012	
ITEM TAX 9.25	
SUBTOTAL	986.93
SALES TAX AMOUNT	91,30
2115.52 1117 11100141	, , JU

SUBTOTAL 986.93
SALES TAX AMOUNT 91.30
TOTAL 1,978.23

2020 AMEN 1 020 22

HARDUARE/SOFTWARE You purchased the following: ASK AN AGENT PRODUCT Serial Nbr: SPACOPCOO1001375045 SERVICE AND SERVICE OPTIONS You want the following service plans : 1. ASK AN AGENT 6 MONTH - 9779167 Note: The \$19.99 discount for Ask an Agent was taken off the price of the computer purchased HARDWARE/SOFTWARE You purchased the following: KASPERSKY AV BOX Serial Nbr: KSP00AV100001461026 SERVICE AND SERVICE OPTIONS You want the following service plans : 6. 3 USER KASPERSKY AV 2 YR - 9815788 HARDWARE/SOFTWARE You purchased the following: REWARD ZONE JOIN SERVICE AND SERVICE OPTIONS You want the following service plans :

You have one last step to become a Reward Zone program member. Please activate your account within 30 days @ MyRZ.com/activate

indicates discount price
 indicates clearance price
 indicates non tax item

YOUR CUSTOMER SERVICE PIN IS: 0170 055 4962 051910

BEST BUY VALUES YOUR FEEDBACK!!
TAKE OUR SURVEY AND ENTER FOR A CHANCE TO
WIN A \$5,000 BEST BUY SHOPPING SPREE!!

Visit http://www.bestbuycares.com Cuestionario en Espanol tambien

& enter the following codes:

Group A: 197

197408

Group B:

5058

Group C:

499764

VO PURCHASE NECESSARY. Must be legal resident of 50 US/DC/PR, 18 or older (except residents of AL and NE who must be 19 years of age or older).

2 Drawing Periods:

3/1/10 - 5/29/10 & 5/30/10 - 8/28/10.

Limit 3 entries per Drawing Period.

For free entry & other details, see Official Rules at website or store.

Void where prohibited.

OUGON to the row of cases products for flowed to the Program Premier Silver me

• AS done for all products for flowed to the Program Premier Silver me

• Labor, desilvery, one-d'or completed installations sorvices

• Labor, desilvery, one-d'or completed installations sorvices



Ship to Address LYNDWOOD UTILITY CORP. SUITE 4 321 BILLINGSLEY COURT FRANKLIN TN 37067 UNITED STATES UNITED STATES

Terms of delivery: FXF,

Payment Terms: Within 30 days

Net weight: 24.300

PRO FORMA INVOICE

Number / Date 20075845 / May/28/2010

Sold to Address LYNDWOOD UTILITY CORP. SUITE 4 321 BILLINGSLEY COURT FRANKLIN TN 37067 UNITED STATES UNITED STATES

Bill-to Customer 204251

Material ID Commodity/COO	Description Batch	Exp.Date	Qı BO İtem	uantity	UnitPrice	Total Value
98-09221-00	WV120SBST	-200, VESSELS	W/S	3	110.00	330.00
3926909910/US 98-21675-00	WQT2K QUA	NTI-TRAY 2000	DI O	2	150.00	300.00
3926909910/US 98-12972-00 3822000002/US	WP020I GA	MMA IRRAD COI	ILE	8	119.00	952.0 0
		_	total t Value amount		USD	1,582.00 80.73 1,662.73

All local taxes at customer charge

TENN. CONTRACTORS, INC.

P.O. BOX 314 FRANKLIN, TN 37065-0314 Phone 615-599-0784 Fax 615-599-0797

DATE: INVOICE #

5/17/2010 1052

Bill To: Lynwood Utility Corporation 180 Cottonwood Drive Franklin, TN

DESCRIPTION			
GROUNDS CLEANUP AND REPAIR		AMOUNT	
	or the second se		
Equipment repair			***************************************
Equipment labor	-	9,800.00	
Manual labor		12,500.00	
Disposal of debris		8,500.00	And the Party of Street, or other Party of S
	-	2,200.00	
		1	
		To all and a second a second and a second an	

		New Prince State S	
		- Milyani in	
	ļ	**************************************	
	OTAL \$	33,000.00	

LYNWOOD HILIT FOR

: bronza cezano & EGUPMENT REPAIR. ALRA , CTAM DEPARA, - Comperson WELDING MAROOTA -BACK W Elesperne Por - beneentan BACK HOE - Back up Diesel Pup. - Sucion Punes PARTS - NAPA - LABOR - Mech -> 6 Hes. 35742 LABOR - Mech 7/4 HD - Suction fune - Fluids Mira - Labor Mech > 9 Hes. - WELDING MACHINE PART. - Lasar - 4 Lles. BACK Hore - PARTS - fuvior _mech - BACK UP F-LECTORAL POPP . PARTS. WIRE -BACK UP DIROFL PIMP - ELLINS

+>

· · · · · · · · · · · · · · · · · · ·	Ealpmet	- Back	Har je	183 21 T	7/08) =	> 7 Dais	#5=/647 = #3SCC
	The second secon	- 160	digar to	ંક ર	*** j	5 hars	Agod Agod Agod Agod Agod Agod Agod Agod
		- Skib 3	TREA	/ / DACIN	5/ -7	7 DATS	**************************************
		- Dompstie	2)	LAGE	0/4	6-8 Duroli	* * * * * * * * * * * * *
e market in the				- L	lain w	DTR - 435	Pylania Olima Pallo
en en a				: ک. <i></i>	icin ha	57 4 - 3 yes	1/2011
		- Thep To	ven	- 5	BAY -	Honorbessy robilization Supplies dans	1095 - FI,500 -
		i i i i	- k A		n	ubilization	& borne !
			MONING	tough	7 2 5	Stope (8) Ham	0
	ABON>	FER	73	Na)	STATE AND	This pre-	\$ 1230 to
· · · · · · · · · · · · · · · · · · ·	BATERS AND TENNESS OF THE STATE OF T	Zichan Th.	28	lin :	المشقي يعالم	LA SILLRAIL	\$
··· ,		Fogus, T	61	ju n ,	the state of	DOES NOW THE WOLLD	
		TELLT	61	1400	\$72 past	ARA ALL	30 T
		VEBANO	73	fi.Fr		to the world	
	~	CAtalino	73	1,2	" in find.	OVER MINT	1410
		Manua 1	73	٠٠ وليا	\$25/14	Der Man	
٠		Micmel T.	71).1 2),	525/161	LIBLERE MON	17amul 1920 =
		Stor Davis	85	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			41 Paps 400 =
		Branos.	85	, r	* North	Marion	
		Michel C.		e at	the Jan	Seemen Time	4.56
	ear	Tyles	_7	2 15	0 - Noch	in He i	Manager on an
		JURYAT		, <u>*</u>	5 - Noem	San Jama Maria (Company)	novernousered
	10 1	and the second s		The sign of the state of the st	-		
11 to 12 11	John Kyrn	>>	ا الاستام ال		6.° 1,-		448,869
	June 1911			Heren	Time &	n deplecem, T	15:304



1021 CHARLOTTE AVE NASHVILLE, TN 37203 Ph: (615) 255-2012

Fax: (615) 255-0311

Sold To

LYNWOOD UTILITY CORP 321 BILLINGSLY CT, STE 4 FRANKLIN TN 37067-6445

Bill To

LYNWOOD UTILITY CORP 321 BILLINGSLY CT, STE 4 FRANKLIN TN 37067-6445

Ship To

LYNWOOD UTILITY CORP 321 BILLINGSLY CT, STE 4 FRANKLIN TN 37067-6445 **Order Confirmation**

*** Re-processed ***

Information

Grainger Order Number Document Print Date

1112264932 09/03/2010

Previous Document Number

Creation Date

09/03/2010

Grainger EIN Number

36-1150280

PO #

SCOTT DAVIS

PO Create Date

PO Release #

Customer Number

865007736

Department Number Project/Job Number

Requisitioner Name

Attention

Caller

SCOTT DAVIS

Telephone Number 615

6155224250 Jermaine - XJCA002

Grainger Contact Name Grainger Contact Phone

6152552012

Grainger Contact Fax

6152550311

Page

1 / 2

Freight Forwarder

We will deliver according to the following terms and conditions:

Incoterms:

FOB ORIGIN

Freight Terms:

Prepaid and Add


Carrier:

Payment Terms:

Net 30 days after invoice date

Special Instructions: on the way

Item PO-Line	Material	Description	Quantity	Unit	Price	Total USD
10	4F740	Pump, Vacuum. 1/4 HP Brand/Model: MOTOR CHANGE FROM 1/3HP TO 1/4H SHIPMENTS. CAT 392 REFLECTS CHANGE.	1.00 IP BEGINNING	EA WITH NO	471.25 V 2000	471.25
20	2ACC9	TRIPLEGUARD 3YR REPLACE	1.00	EA	89.95	89.95
					ub Total ax	561.20 51.91
				To	otal Amount	\$ 613.11



TENN. CONTRACTORS, INC.

P.O. BOX 314 FRANKLIN, TN 37065-0314 Phone 615-599-0784 Fax 615-599-0797

DATE: INVOICE #

5/17/2010 1003

Bill To: Lynwood Utility Corporation 180 Cottonwood Drive Franklin, TN

DESCRIPTION		AMOUNT
Detailed inspection of 104 manholes in Cottonwood Subdivision. Above ground inspection of 25,000+ L.F. of collection system lines.		\$ 1,875.00
	TOTAL	\$ 1,875.00

COTTONWOOD SUBDIVISION MANHOLE INSPECTION

5/17/10

On May 17, 2010, Tenn. Contractors Inc. was hired to inspect 104 manholes in Cottonwood subdivision. The inspection results were as follows.

Five manholes were reported with leaks, manhole #'s 3,18,83,90, and 104. Leaks were measured in gallons per minute (gpm) as shown in the table attached. Two manholes require 4" risers (manhole 73 and 95). Two other manholes require casting repair (4 and 22). Manhole # 92 has broken casting as well as roots coming in from lateral. All other manholes were reported as good condition. All manholes were poured in place, with the exception of manhole #56 which is made out of brick and mortar.

Attached is a table of all 104 manholes in Cottonwood subdivision that shows condition of manhole, flow of waste water, leaks, and comments. Also attached is a plan that shows location of all manholes.

Cottonwood Subdivision

Manhole inspection 5/17/10

1	e # Condition Good	n Flow Heavy	Leaks Y/N T N	Comments
<u>.</u>	Good	Heavy		The state of the s
<u></u>	Fair	Heavy	$\frac{\lambda}{4}$	
	Fair	Medium	PERSONAL PROPERTY OF THE PROPE	Two leaks @ 6 gpm
5	Good	AND ASSESSMENT OF THE PROPERTY	<u> </u>	Concrete around casting is missing (1/4)
<u>ე</u>	Good	Medium	<u> N</u>	
<u></u> 7	CHIERCE CONTRACTOR OF THE CONT	Heavy	<u>N</u>	
<u>′</u> 8	Good	Medium	<u> </u>	
<u>o</u> 9	Good	Medium	N	Asphalt built up on M.H. casting
10	Good	Medium	N	
Miles management and a second	Good	Medium	N	
11	Good	Medium	<u>N</u>	Concrete around casting is corroding
12	Good	Light	N	Water tight manhole
13	Good	Medium	<u>l</u> N	Bolt fastered M.H.
14	Good	Medium	N	Bolt fastered M.H.
15	Good	Light	<u>N</u>	Boit fastened M.H.
16	Good	Light	N	
17	Good	Light	N	
18	Good	Light	N	
19	Good	Light	N	SECURION AND AND PROPERTY OF CHARACTER OF THE SECURIOR SE
20	Good	Light	N	
21	Good	Medium	N	
22	Good	Medium	N	Needs casting Repair
23	Good	None	N	many result in 1720011
24	Good	Medium	N	
25	Good	Light	N	
26	Good	None	· N	
27	Good	Light	N	
28	Good	Light	<u>N</u>	
2 9	Good	None	N I	
30a	Good	THE RESERVE OF THE PARTY OF THE	N	
30	1-900	Light		
31	Good		movement of the second	Manhole not inspected. Need to remove pavemen
32	Secure resemble to the second secure resemble to	Light	N. L	Water tight manhole
32 33	Good	Light	N	
<u> 33</u>	Good	Light	N	
35	Good	None	N	
CONTROL CONTRO	Good	None	N	
36	Good	None	NI	
37	Good	Light	N	Water tight manhole
38	Good	<u>Light</u>	N	
39	Good	None	N	The state of the s
40	Good	Light	N	The state of the s
11	Good	Light	N	
12	Good	Light	N	OR A COLUMN AND THE SEASON OF T
13	Good	Light	N	
4	Good	Light	N	
5	Good	Light	N	

grabit married and a con-	dilitara anno anno anno anno anno anno anno a			
46	Good	Very Littl	e N	Rags were found and removed from invert.
47	Good	Light	N	The second secon
48	Good	Light	I N	
49	Good	None	N	THE CHANGE AND ADDRESS OF THE CHANGE AND ADD
50	Good	Light] N	
51				Manhole not inspected. Need to remove bushes.
52	Good	None	T N	The second secon
53	Good	Light	T N	- CONTRACTOR CONTRACTO
54	Good	Light	N	
55	Good	Light	l N	
56	Good	Light	T N	Made of all brick and mortar
57	Good	None	T N	
58	Good	None	T N	
59	Good	Light	T N	Manhole is located inside home owner fence
60	Good	Light	T N	
61	Good	None	TN	Little die des la company de l
62	Good	Light	N	
63	Good	Medium	N	
64	Good	Light	IN	
65	Good	Light	Ň	
66	Good	Light	T N	
67	Good	Light	N	
68	Good	Light	l N	
69	Good	None	l N	
70	Good	Light	N	
71	Good	None	N	
72	Good	Light	N	
73	OK	None	N	Need to add 4 inch riser to manhole
74	Good	None	N	Modern to control to the transfer of the trans
75	Good	None	N	
76	Good	None	N	
77	Good	None	N	
78	Good	None	N N	
79	Good	Light	N	
80	Good	None	N	
81	Good	Light	N	
82	Good	Light	N	
83	Fair	Light	<u></u>	1 look & 1 A
84	Good	Light	N	1 leak @ 1-2 gpm
85	Good	Light	N	N. S. J. Constitution of the Constitution of t
86	Good	Light	N	M.H. casting was slightly off
87	Good	Light	N	Acrical audition and the second
88	Good	Light	N	Asphait built up on M.H. casting
89	Good	Light	N	
90	Fair	Light	Y	
91	Good	Light	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	1 loak upstream @ 3 gpm
92	Good		N	
The constitution of the co	 	<u>Light</u>	IA I	Casting is broken. Large amount of roots in M.H.
93	Good	Links		Roots coming from Lateral
94	Good	Light	N	
95	Good	Light	N	
95 96	Good	Light	N	Need to add 2" riser
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		None	<u>N</u>	Inside mulch bed. Buried.

gasses January America

97	Good	None	N T	
98	Good	Light	N	
99	Good	Light	N	
100	Good	Light	N	
101	Good	Light	N	
102	Good	Light	N	Large amount of soil covering M.H.
103	Good	Light	N	reade guidalle of soil coastilla latin
104	Fair	Medium	Y	1 leak in middle service @ 5-6 gpm



#### SPECTRUM EQUIPMENT PARTNERS LTD.

3411 GARTH ROAD, # 215 BAYTOWN, TX 77521 PH: (225) 686-1003 FAX: (225) 686-1016

sdomangue@spectrumequipment.com

5/5/2010

23171

Lynwood Utility INC. 321 Billingsly Court

Ste 4

Franklin, TN 37067

and the second

180 CottonWood DR Franklin, TN 37069

1 June 7 19 - 1 2 5-10-10

Net 30

SD

5/5/2010

6 Flt-30-ST Filter Screen - 30 Yd. Turbo 195.00 1,170.00

1 S&H/FRT Shipping & Handling 118.00 118.00 Out-of-state sale, exempt from sales tax 0.00% 0.00

# abtronX, Inc.

501 Metroplex Dr., Suite 109 Nashville, TN 37211

# Customer Invoice/Bill

DATE	INVOICE#
7/1/2010	AA020920

BILL TO	
Lynwood Utility Corporation	
Accounts Payable	
321 Billingsly Court., Suite 4	
FRANKLIN TN 37076	

SHIP TO LYNWOOD UTILITY COMPANY 321 BILLINGSLY CT., SUITE 4 FRANKLIN, TN 37067 Per: Scott Davis, 604-2902

P.O. NO.	TERMS	DUE DATE	TECHNICIAN	WORK	SHIP COMPLETE	REGION
Verbal-Scott Davis	Net 30	7/31/2010	nc		7/1/2010	Mid-TN
DESCRIPT		S/N	HRS	/QTY	RATE/COST	AMOUNT
Accuracy Assurance: Clean, Periodic Maintenance on Lab Inline Equipment per Work Ord Sales Tax	Equipment and/or	7			240.00	-
Sales I ax					9.25%	22.20
	/					
	135					
			A Control of the Cont			
			The second secon			
				Andreas de Constitución de la co		
				and the second s	THE CAMPAGE AND ADDRESS AND AD	
		- Marian dia mandri dia kaona d				

Labor & parts replaced are guaranted for 30 days from invoice date. A service charge of 1.5% per month will be added to unpaid balances on all past due invoices. Please pay from this invoice.

REMIT TO: LabtronX, Inc., 501 Metroplex Dr., Suite 109, Nashville, TN 37211 Phone 615-831-2554/800-830-2554 / FAX 615-831-2498

We now accept VISA, Mastercard & American Express.

Total

\$262.20

# TENN. CONTRACTORS, INC.

P.O. BOX 314 FRANKLIN, TN 37065-0314 Phone 615-599-0784 Fax 615-599-0797

DATE: INVOICE #

5/16/2010 1054

Bill To: Lynwood Utility Corporation 180 Cottonwood Drive Franklin, TN

DESCRIPTION	,	T	AMOUNT
PLANT BASIN CLEANING AND REPAIR			SOUCH!
Aeration Basin #1- repair wall joints and cleaning			( 000 -
Neration Basin #2- repair wall joints and cleaning			4,200.00
, and and an			4,200.00
	TOTAL	\$	8,400.00

John Rynn

Lynneso HATT

PROSERS: ARATON BEIN REPAIR (CLEANING & FRANK)

15124 : Fact BOLD HOLD. 1 123,000 GALLANS

48 2

MATTERIAL: - 200 DISC DIESENER MEMBERIES.

- C'llamps for 4" "IL TIE Thin

- Froxy : 2 (ASE)

Equipment Pagesson - 3 Days " Compages son - 3 Days " Compages on - 3 Days " Compages o

: Mirmel C. - 32 HRY Stytha toward struck Text VRBAND 31 m) Depth with me · COMMATON) 32 K2) The file of the second desire - MANUAL 32 HR) Deplet CABOL BAT Aven 32 UD. They have the same of the - Branco-Halfe in Sween out gast 22 119. * 1 主英心 华 - Simmer Asylan Sweether KATT 37 NP : 7, st BROOMS

SUPPLIE : 213H

Prist SROOM) South

· Bank) - 26 77

Se Tr 10.985

010/01414

#### ATLAS SEPTIC & GREASE REMOVAL

John & Jennifer Roy - Owners/Operators P.O. Box 463 FRANKLIN, TN 37065

٨	(615) 794-0960 395	-4594
	461 Ring 395	
HILLAND	YNDWOOD Utilly	31110
ADORES	Cotton word &	V
	PA	E
SOLD BY	CASH C.O.D. CHARGE CHAC	CCT. LEOSE RETO
ODY.	DESCRIPTION	AMOUNT
	UESCHIFTION	AMOUNT 3
2.0	10 11 h.f 17060 G	1650 0
5-11-	10 12hr 40004	1800 00
SIL	6 4hrs	100,00
	71100 a	and the second s
7	1-26-14	
LUI	prhau	
,		
1-	1,590 = NO	<b>)</b>
	MUII	
	And the second s	
	and find to the other field and four particular extensions that out the contribute distribution for the time that they distribute the time.	on the same of the
and the second s		1
	Section for the first control was remainded additionally a mark or plant on process and market and restrict an expensive above to remain an expensive and the control of th	
	The state of the s	
RECSIVEO B	TA	
	TOTAL	4050100
	0895	Thank You
	All elvings and an annual	

Work Jone on 5-10-10 5-11-10 5-12-10

May 13 10 01:42p

## ATLAS SEPTIC & GREASE REMOVAL

John & Jennifer Roy - Owners/Operators P.O. Box 463 FRANKLIN, TN 37065 (615) 794-0960 395-6934

٤	Inch lang.	
NAME	MINUSCH UTULE	1 S-8-10
Alames (	STUDLED PROBE	
SOLD BY		
ary.	CHARGE ON ACCT.	MOSE RETO
137	DESCRIPTION	AMOUNT
116	84.	15400 -
15/	bler	1400 -
		600 -
	2	
	ump & tarl	
	7	
-	thank ton	
-	No. I	
	11110	
-		
CEVEO BY	TAX	
-decomposition to the second s	TOTAL	3400,00
	0891	ank You
	As claims and enterned goods MUST by accompanied by this bit	WALK TOU



### LYNWOOD UTILITY CORP.

321 BILLINGSLY CT, SUITE 4 FRANKLIN, TN 37067 87-854-641

5/8/2010

PAY TO THE ORDER OF

ATLAS SEPTIC & GREASE REMOVAL

\$ **3,400.00

PEZED SEGNATURE

DOLLARS

ATLAS SEPTIC & GREASE REMOVAL P O BOX 463 FRANKLIN, TN 37065

MEMO

Flood

LYNWOOD UTILITY CORP.

ATLAS SEPTIC & GREASE REMOVAL

Flood

5/13/2010

4,050.00

228

Tennessee Commerc Flood

4,050.00

### TENN. CONTRACTORS, INC.

P.O. BOX 314 FRANKLIN, TN 37065-0314 Phone 615-599-0784 Fax 615-599-0797

DATE: INVOICE # 5/17/2010 1051

Bill To: Lynwood Utility Corporation 180 Cottonwood Drive Franklin, TN

DESCRIPTION		AMOUNT
BUILDING CLEANUP AND REPAIR		
Removal of debris, mud, and garbage from inside of building		2,000.00
Cleaning of laboratory		750.00
Cleaning of Mechanical rooms		750.00
a.	TOTAL	\$ 3,500.00
a = a + b + b + b + b + b + b + b + b + b +	IOTAL	Ψ 3,500.00
Sulm Ch Mi		
July My Mr.		

PROJECT SOURCE WAS TRANS.  CLEANING SE FE LINGUIS THE CLEANING SERVICE.  CLEANING SE FROM ADDRESS.  REGION OF TODAY MAY LEGISTED.  FRESSORE WASHER DAY BY TO THE SUPPOSED. SELECT STOCK.  LANCE SHAS FRANCE SUPPOSED. SELECT STOCK.  LANCE SHAS FRANCE SUPPOSED. SELECT STOCK.  LANCE SHAS FRANCE SUPPOSED. LANCE FOR SHOCK.  CHECKER SHAS FRANCE SHAPE SHOCK.  MICHAEL SHAS FRANCE SHAPE SHOCK.  MICHAEL SHAPE SELECT.  MICHAEL SHAPE SELECT.  MICHAEL SHAPE SELECT.  MICHAEL SHAPE SELECT.  MICHAEL SHAPE	LYNWOOD VILLIET	6070 - Bu	70			to the second of
CARNER OF THE LEGION STATE  CRANNER OF THE PROPERTY OF THE THE SERVER WASHER DAY AND I DAYSTER OF HERE  LABOR THE SEAS FRAME LAW IN 6160 TO SEAS FRAME SEAS THE SEAS				PERMIZ.		tion of the state
Equipment of Tobs was been as Tobs of was a tobs of the control of					1	
Equinor of Tobot mo, 6 voto:  Equinor T  Pressure where Day  Dapster 940/400 I Dapster 94000  LASCA  Are Sus 520/400 Line int \$160 -  Char Sus 520/400 Line are \$160 -  CHECLUS Sus 520/400 Line are \$160 -  CHECLUS Sus 520/400 Line are \$160 -  Michiel S His \$80/400 Line Rook \$160 -  Mich	The second secon	CRAMING SE M.	Ecin . Po	oms.	· · · · · · · · · · · · · · · · · · ·	to the terminal of
PRESSURE WASHER DAY  DIMPSTERS 400/HALL 1 DIMPSTER . 5140000.  LABOR.  HUEL S HER SZO/HAL LAW LAT \$16000000000000000000000000000000000000	-2	Monal as The	bet mo	, Croth		
PRESSURE WASHER DAY  DIMPSTERS 400/HALL 1 DIMPSTER . 5140000.  LABOR.  HUEL S HER SZO/HAL LAW LAT \$16000000000000000000000000000000000000	and the second of the second o	·				
PRESSURE WASHER DAY  DIMPSTERS 400/HALL 1 DIMPSTER . 5140000.  LABOR.  HUEL S HER SZO/HAL LAW LAT \$16000000000000000000000000000000000000	Ealiment	······································				
DADRESS 400 / HARL   DADRESSER. 54 40.000.  LABOR.  ALEC S 1129 520/HA. LASOL LATE \$ 160 2  BUILDING S 160 5820/HA. LASOL LATER FORK \$ 160 2  COTTRILLO S 160 520/HA. LASOL RATE \$ 160 2  MICHARLO S 160 520/HA. LASOL RATE \$ 160 2  MICHARLO S 160 520/HA. LASOL RATE \$ 160 2  MICHARLO S 160 520/HA. FOREMAN A TRULE \$ 640 -  BUILDING - 8 100/HA. \$ 550 -  MATERIAL S 160 5 2  MATERIAL S 160 5 2  MATERIAL S 160 5 2  MATERIAL S 160 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5 300 5			DAY	er er	• • • • • • • • • • • • • • • • • • •	£ 75°°.
### S H25 \$ 20/H0 LADY EAT \$ 160 -  NAME S H2 \$ 20/H0 LADY EAT \$ 160 -  NAME S H2 \$ 20/H0 LADY EAT \$ 160 -  CATELLYO S H2 \$ 20/H0 LADY EAT \$ 160 -  MICHAEL T S H4 \$ 20/H0 LADY EAT \$ 160 -  MICHAEL T S H4 \$ 20/H0 LADY EAT \$ 160 -  MICHAEL T S H4 \$ 20/H0 LADY EAT \$ 160 -  MICHAEL T S H4 \$ 80/H0 FORTHON & 1640 -  ELECTRICAL S H47 \$ 80/H0 FORTHON & 1645 -  MATERIAL THE PARTY SHAPE S H45 -  CADAMIT REPARTY = LADY & MATERIAL \$ 300 -  SHAP MATERIAL S LADY & MATERIAL \$ 300 -  SHAP MATERIAL \$ 320 -  SUBTICE \$ 3650 -  DISCOUT - \$ 150 -	DMXTER	2 - 40c	/ HALL	1 Daps	<b>U</b>	9 40000
### S H25 \$ 20/H0 LADY EAT \$ 160 -  NAME S H2 \$ 20/H0 LADY EAT \$ 160 -  NAME S H2 \$ 20/H0 LADY EAT \$ 160 -  CATELLYO S H2 \$ 20/H0 LADY EAT \$ 160 -  MICHAEL T S H4 \$ 20/H0 LADY EAT \$ 160 -  MICHAEL T S H4 \$ 20/H0 LADY EAT \$ 160 -  MICHAEL T S H4 \$ 20/H0 LADY EAT \$ 160 -  MICHAEL T S H4 \$ 80/H0 FORTHON & 1640 -  ELECTRICAL S H47 \$ 80/H0 FORTHON & 1645 -  MATERIAL THE PARTY SHAPE S H45 -  CADAMIT REPARTY = LADY & MATERIAL \$ 300 -  SHAP MATERIAL S LADY & MATERIAL \$ 300 -  SHAP MATERIAL \$ 320 -  SUBTICE \$ 3650 -  DISCOUT - \$ 150 -	The second secon			was a second	to the second second	e de la companya de
######################################	一一一一一一一一一				the second of the second	the second se
MINISTER SUES \$ 20/14 LABOR EATE \$ 160 -  CATERLUC S HAS \$ 20/141. LABOR FATE \$ 160 -  MICHIEL S HAS \$ 20/141. LABOR FATE \$ 160 -  MICHIEL S HAS \$ 80/141. FORFATO & TRUE \$ 640 -  RATERIAL BOOKS & HAS \$ 100/141. \$ 550 -  MATERIAL BOOKS & HAS BOOKS & MATERIAL \$ 300 -  CARNET REPAIR = LABOR & MATERIAL MATERIAL \$ 300 -  SUB TTL \$ 3650 -  DISCONT - 5150 -	and the second of the second o		S 423	\$ 20/10.	LA RE- DATE	160
DUMMY S WS \$20/W LABOR RATE \$160 -  (**TELLUC S WS \$20/W, CASER RATE \$160 -  MICHATIC S HA \$20/W, LABOR RATE \$160 -  MICHATIC S HA \$80/W. FORTON & TRUE \$640 -  RATE.  BUTCHELLOW & HA & 80/W. FORTON & TRUE \$640 -  RATE.  WATERIAL	The second secon	UBAN C	S 1191	\$ 20/Ha	LAPSE BATE	\$ 1662
( TTELLY C S HE \$20/HD, LASER ROTE \$ 160 -  MICHICC S HE \$20/HD, LASER ROTE \$160 -  MICHICC S HE \$80/HD. FORFRED & TRULK \$640 -  ELECTRICAL S HE \$ 100/HD. \$850 -  MATERIAL SHAPE - SILES -  MATERIAL SHAPE - LASE & MATERIAL \$300 -  SUBJECT \$3650 -  DULLY \$3650 -  DULLY - \$150 -	en e	PANAC	Sues	5420/iUn		* 160
MICHAEL T. 5 HB \$20/10. LABOR RATE \$160 =  MICHAEL C S HA \$80/10. FORFIND & TRUE \$640 =  RATE DIAC.  BLESDICIAN - S HD; & JON/APR. \$850 =  MATERIAC.  BESSAN;  BOOD  MASKER:  LEWY  CARRET REPARE = LABOR & MATERIAL - MATERIAL \$300 =  8 HD; 49/HR, LABOR \$300 =  SUBSTITE \$3650 =  DISCOUT - \$150 =	secretaria de como que als como especialmente al seco.	CATELLIO				The state of the s
MICHTICC SHA +80/W. FORTING 1 TRUE \$640 - 2 2 4 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	and the second of the second o	Microel T.		£ _ 1		A contract of the second secon
BLERRICH - 8 H2; & 100/149. 3500-  MATERIAC.  BESSON;  BOOTS  MASKI.  LINK.  CARNET REPAIR = LABOR & THATERIAL 5300"  8 482 49/42 (4500. 320"-  SUBTIC "3650"-  DUSCINE - 5150"-		MICHTEC C				\$640
Bessn;  Bessn;  Bessn;  MASKI.  Livia,  CARNET REPAIR = LASSE & MATRIT - MATRIA 5300"  8 482 40/48. LASSE 320"  SUSTIC 3650  DISCUIT - 5150"		Blackup	- S W			
MASKI.  LIANI,  CAPANAT REPAIR = LABOR & MATERIAL \$300"  8 40, 40/42. LABOR \$300"  SUBTTL \$3650  DISCONT - \$150"	WATEPIAC .	ř(N)	中国现代	- parameters -	i e e e e e e e e e e e e e e e e e e e	\$1.465°Z
MASKI.  LOWER,  CARNET REPARCE = LABOR & MATERIAL "300"  8 48, 40/40. (4340. "320"  SUBTTC "3650  DISCONT - 5150"	The state of the s	Bosan;	-	······································	14 T - 1884 1	The state of the s
CARAMIT REDACE = LABOR & MATERIAL -MATERIAL 5300"  8 402 40/42 (4300 320"  SUBTIC 3650  DISCOUT - 5150"		Bero				31602
CARMET REPAIR = LABOR & MATERIAL -MATERIAL 5300"  8 102 40/40. LABOR 320"  SUBTTC 3650  DISCOUT - 5150"	A. V. M. KV) M	MASKI.	N. A.			
8 402 40/42. CABUR. 320- SUBTTC 3650 DISCOUT - 5150-	JAN VI TI	Link	- /	1 W	the second second second	and the second of the second o
8 402 40/402 CABUL 320"- SUBTTC "3650 DISCOUT - \$150"-	CADART &	E1462 = L	484	z Matrz	YL -WATROIG	\$300
SUSTIC *3650 DISCOULT - \$150 =	The state of the s	1 - 1 <del>114</del> 5 -	·· <			was a second of the second of the second of
	Control of the Control of Control				SUB TTC	* 3650
					A STATE OF THE PERSON OF THE P	

## TENN. CONTRACTORS, INC.

P.O. BOX 314 FRANKLIN, TN 37065-0314 Phone 615-599-0784 Fax 615-599-0797

DATE: INVOICE #

5/22/2010 1053

Bill To: Lynwood Utility Corporation 180 Cottonwood Drive Franklin, TN

DESCRIPTION	AMOUNT	
CONCRETE WORK		
Concrete, Steel, and Labor (\$5.00 per square foot)	,	8,700.00
Concrete Slab		3,700.00
#4 bars at 12" O.C.		
Curb included		64 ************************************
Additional storage patio		
Additional footing for landscape retaining wall		
1	TOTAL	\$ 8,700.00
Jehn right	•	
Applin 129/12		

SRE APRIM 1750 \$ 185 50 1950

1	Dock (was is	non e membrosis— como, s	~	
Enisi.		1	£ 20.25 <b>4.</b> 6	- 1
	CONCLESE.	₹.61	64/2403 31.20	i
n de la martina de la companya de l La companya de la companya de				
FOOTER.	->E	Vinta di Managari		· A constraint
	20 1		A STATE OF THE STA	

MATERIA	CONCRI	30 cv. ya	CONCERTE	(Appan)	e 1422
				12" CENTERS	
* **		- 6 = 6 × 1 4 v			\$ \(\frac{1}{2}\) \(\frac{1}{2
				15E. 2000 2	
Equiment				(LES) = 142.	4 6C
	PUBBER TIC	in. Botch hi	w : Dar.	12 10 Km	
	PLATE	7Amp -	3 Kas	1921 for a par o	mil 1257
	- COMPETE	From;	- 2×4 Ta	charges links	
· ·			- 2x6 T	ment in the	
	- Dang 4-	eulic - 2	- 228 BATS	make how	* Leon
ABOR:	- Vrbano	14_		in para	5 231
	- CATALINA	M	/ *11.14		
and the second s	- Marian	; L!	Z man Mai	LA MOR	# 28.1
Manage 49	Maero	iser sand that if	N. (1988)	7 XC	
	- Mire C	16		The section of the se	1 1280
	- Micha! T.	! 4	A Last Johnson	L. LASSE PATE.	\$ 44.0
Sugar	) m	**	t 2.	<b>~</b>	

John Ryth

NHAM BADA

Floating Bases - Glas

That has saled. There's

10 339 E



Franklin Dispatch: (615) 794-6671
Nashville Dispatch: (615) 367-2918
Main Office: (615) 794-2552
Fax: (615) 794-6939

SALES INVOICE

Sold To: TENNESSEE CONTRACTORS, INC.

P O BOX 314

FRANKLIN TN 37065-0314

Customer Account Number: T160

Project Description:

Project Number:

Invoice Number: 130196

Invoice Date: May/18/2010

Delivery Address:

COTTOMOOD

Purchase Order:

Terms:

\$1/CY BY 10TH, NET 30TH

Ticket Date	Product	Product Description	Plant	Ticket	Quantity	Price	Extended Price
	1 R140 R140	4000X PSI WITH RETARDER 4000X PSI WITH RETARDER	1	118831 118839	10.00 cy 3.00 cy	77.50 77.50	775.00 232.50

Discount of \$ 13.00 may be taken if Invoice Total is paid by Jun/10/2010

Total CY Sub Total Sales Tax TOTAL 13.00cy 1007.50 93.20 1100.70



Franklin Dispatch: (615) 794-6671 Nashville Dispatch: (615) 367-2918 Main Office: (615) 794-2552 Fax: (615) 794-6939

#### SALES INVOICE

Sold To: TENNESSEE CONTRACTORS, INC.

P O BOX 314

FRANKLIN TN 37065-0314

Customer Account Number: T160

Project Description:

Project Number:

Invoice Number: 130117

Invoice Date: May/13/2010

Delivery Address:

Purchase Order:

Terms:

180 COTTONWOOD DR

CALLING WHEN LOADING \$1/CY BY 10TH, NET 30TH

Ticket Date	Product	Product Description	Plant	Ticket	Quantity	Price	Extended Price
Order Code:	17						
May/13/2010	R140	4000X PSI WITH RETARDER	1	118786	6.00 cy	77.50	465.00
May/13/2010	FM	FIBERMESH	1	118786	6.00 ea	5.00	30.00
May/13/2010	R140	4000X PSI WITH RETARDER	3	381160	10.00 cy	77.50	775.00
May/13/2010	FM	FIBERMESH	3	381160	10.00 ea	5.00	50.00

Discount of \$ 16.00 may be taken if Invoice Total is paid by Jun/10/2010

INVOICE TOTAL

Total CY Sub Total Sales Tax 16.00cy 1320.00 122.10 1442.10

228QUTHVTI



						date (seedintyy)
ACORD.	endence of Prop	erty inguran	ICE	•	.5 4.	
	NICE IS NOLES AS A SATTOR OF NEVOES					
The state of the s	//magestical articles, cause		AV, Commission	7 7749 6731.4	3 (10)	
Acciev	915 252-5989	- Residend the Co of the		•		
70B (13)		Marine Cress				
		P. O. Box 0009-2370	3			
		Reno, MV 80004				
75 LL 7-7 07-3417	San Term					
6332						
6. 4. 6.4.63		- LCAN HISSER	POLICY	20000000000	***************************************	CONTROL OF THE PARTY OF THE PAR
RESIDENCE OF THE PARTY OF THE P	car Aba	LIZAM WINNESSER	979443		}	
7 P. 14		SPRECTARE DATE	COPULATION			55 111
Franksia, TVI S7057		84/17/10	94/17/N			ATTO IF CHECKED
		THIS REPLACES PRICE SYS	ENCE DATED:	···	LL	
*						
		and the second s			- Torontono e e e e e e e e e e e e e e e e e e	
				HE-MAN-HOLDON TO AND	egenneg de legen de generalistic de la company de la compa	Transport of State State of the State of State State State of State S
Frenicis, TN 97034 Stabiling 91						
ा रहे साथ के के किया है। विकास						
್ ಕೃತ್ತಿಕೆ ಎಕ್ಕ್ಟ್ ಮಾತ್ರಿಕೆ ಕೃತ್ತಿಕ ಬೈತ್ರಿಕೆ ಎಕ್ಕ್ಟ್ ಮಾತ್ರಿಕ						
	TO SELCON HAVE SEEN ASSUED TO	7VE 010 0050 MARKED AND	har son ma	F PCI ICY	sando ed	ezaven
Grand Co. A. T	NEST, TERM OR CONDITION OF AW	COMPACT OR OTHER	OCIDADIT		PICT TO W	0CM 7069
	ELL MAY BE MALLED CALMAY PLACE	n, republikan		he Polic		
	LUDICIUS AND CONDITIONS OF SUC	HOLGES LANS SKA	RI CLAY HAVI	EULENM	20,000,007	PAD CLAMB.
					······································	
	00/03/4/2000/2000/2000/2000/2000/2000/20			ASSESSIT OF	'CANA	222337318
				<u> </u>		
Commandel Property Policy Lov						
Commercial Property Policy Lev Commercial Ridding				223,000		\$1,500
Commercial Property Policy Lev Commercial Ridding						
Commanded Progenty Policy Lev Coverage: Building Cases: Plood	el Coverages					
Commanded Progenty Policy Lev Coverage: Building Cases: Plood	el Coverages					
Commarded Progenty Policy Lev Coverage: Building Cases: Plood Tood Location Specific Coverag	el Coverages					
Commercial Property Policy Lev Coverage: Building Names: Plood Hood Location Specific Coverag See Attached Coverage Info.)	al Coverages					
Commardist Progenty Policy Lev Coverage: Building Cases: Plood Food Location Specific Coverag See Attached Coverage Info.)	al Coverages					
Communical Property Policy Lev Concease: Building Cases: Flood Flood Location Specific Coverag See Attached Coverage Info.)	al Coverages					
Communical Property Policy Lev Coverage: Building Cases: Flood Hood Location Specific Coverag See Attached Coverage Info.)	al Coverages					
Communical Property Policy Lev Coverage: Building Cases: Flood Hood Location Specific Coverag See Attached Coverage Info.)	al Coverages					
Communical Property Policy Lev Coverage: Building Cases: Flood Hood Location Specific Coverag See Attached Coverage Info.)	al Coverages					
Communical Property Policy Lev Coverage: Building Cases: Flood Food Location Specific Coverage See Attached Coverage Info.)	al Coverages					
Communical Property Policy Lev Coverage: Building Cases: Flood Food Location Specific Coverage See Attached Coverage Info.)	al Coverages					
Communical Property Policy Lev Coverage: Building Cases: Flood Food Location Specific Coverage See Attached Coverage Info.)	al Coverages					
Communical Property Policy Lev Coverage: Building Cases: Flood Food Location Specific Coverage See Attached Coverage Info.)	al Coverages					
Communical Property Policy Lev Coverage: Statisting Cases: Plood Food Location Specific Coverage See Attached Coverage Indo.)	al Coverages					
Communical Program's Policy Levicement, Building Causes: Plood Pood Location Specific Coverage See Attached Coverage Info.)  EMARKS Suchebus Specific Coulds  MARKS Suchebus Specific Coulds				530,000		\$1,203
Commanded Progenty Policy Lov Coverage: Building Smee: Plood Food Location Specific Coverage See Attached Coverage Info.)	d Coverages	DE ATTOM THE PERSON ASSESSED THE SEAD		500,000		\$1,208
Commanded Progenty Policy Lov Coverage: Building Sees: Plood Food Location Specific Coverage See Attached Coverage Info.)		DE ATTOM THE PERSON ASSESSED THE SEAD		500,000		\$1,208
Communical Property Policy Levicescops: Building Causes: Plood Food Location Specific Coverage Info.)  Black Schooling Specific Coverage Info.)  Black Schooling Specific Coverage Info.)	d Coverages	LCM, BUT FIRLUIS TO HAL	THE SECOND SECON	500,000		\$1,208
Communical Property Policy Low Coverage: Building Sauce: Flood Food Location Specific Coverage See Attached Coverage Info.)	d Coverages  Sees)	R.GM, BUT FALLISE TO MAR.  X MONTGAGES		500,000		\$1,203
Communication Property Policy Lov Concess: Planting Concess: Plant	d Coverages  See 1	X MENTGAGEE LOGS PAYEE	THE SECOND SECON	500,000		\$1,203
Commercial Property Policy Lov Concess: Establing Concess: Pland Flood Location Specific Coveres See Attached Coveres Info.)  ENAMES Section Specific Coveres  ANCELLATION DULD ANY OF THE ASSAULT CONTEST  (AND ANTEST  Technology Contests on Red  301 Mailory Station Red	d Coverages  See 1	R.GM, BUT FALLISE TO MAR.  X MONTGAGES	THE SECOND SECON	500,000		\$1,203
Commercial Property Policy Lov Corresponding Control C	d Coverages  Seek L, Suite	X MENTOAGEE LOGS PAYEE	THE SECOND SECON	500,000		\$1,203
Commercial Property Policy Lov Concess: Establing Concess: Pland Flood Location Specific Coveres See Attached Coveres Info.)  ENAMES Section Specific Coveres  ANCELLATION DULD ANY OF THE ASSAULT CONTEST  (AND ANTEST  Technology Contests on Red  301 Mailory Station Red	d Coverages  Seek L, Suite	X MENTGAGEE LOGS PAYEE	THE SECOND SECON	500,000		\$1,203

#### COVERAGE INFORMATION (Continued from page 1.)

COVERAGEPERLEPONIES	ASSOCIATION DESIRANCE	E DEDOCTBLE
ocation #: 1 188 COTTONWOOD LANE Franklin, TN 37064		
Coverage: Building	<b>4</b>	
Limit1:	175,000	\$1,000
Consequent to account Comb of Committees on Commit		
Coverage: Increased Cost of Compliance Premium		
	ì	\$
Coverage: Community Rating System Discount	;	
	•	\$
Ф., ор и ст	i i	
Coverage: Policy Fee		1_
	•	\$
Coverage: Additional Flood Building		
imiti:	325,000	\$1,000
		1
ood Coverages		
~~ ~~~	1	
cation & 1 188 COTTONWOOD LANE Franklin, TN 37064	***************************************	
uliding 8: 1	·	
all ding	500,000	500
CIT COLORES	125,000	- Control of the Cont
	1	
	<u>;</u>	
	:	
	ļ	
	;	
	4	
	:	
	1	
	1	
		-
		***
		· ·
	*	-
		1



COMMERCIAL LINES POLICY COMMON DECLARATIONS

REMEMAL OF CL9 0087927

#### NON-ASSESSABLE

	NOTICA MINISTRA TITLE SOLKA LEMOO	***************************************	FE FE BOOK & PART 1 20 COME CONTRACTOR OF THE PARTY OF TH
	CL9 0087927 09/01/09 09/01/10	***********	COVERAGE IS PROVIDED IN AGENCY DR
	03/01/03 03/01/10	P	A MATIGNAL BUTUAL CAS INS CO 000824005
	NAMED INSURAD AND ADDRESS	1	AGENCY
	SOUTHERN UTILITY CORPORATION  EYNAGOD UTILITY CORPORATION  321 BILLINGSLY COURT SUITE 4  FRANKLIN TN 37087		BB&T INSURANCE SERVICES PO BOX 139 NASHVILLE IN 37202
Ł.			***Physioletistation in bringing in the control of

POLICY PERIOD: POLICY COVERS FROM 12:01 AM STANDARD TIME AT THE ADDRESS OF THE INSURED STATED ABOVE. FORM OF BUSINESS: CORPORATION BUSINESS DESCRIPTION SEWER PLANT

IN RETURN FOR PAYMENT OF THE PREMIUM, AND SUBJECT TO ALL THE TERMS OF THIS POLICY, WE AGREE WITH YOU TO PROVIDE THE INSURANCE AS STATED IN THIS POLICY.

THIS POLICY CONSISTS OF THE FOLLOWING COVERAGE PARTS FOR WHICH A PREMIUM IS INDICATED. THIS PREMIUM MAY BE SUBJECT TO ADJUSTMENT.

TOTAL TOTAL PROPERTY S.		PREMUM
COMMERCIAL PROPERTY COVERAGE PART	\$	2,940.00
COMMERCIAL CRIME COVERAGE PART	s	
COMMERCIAL GENERAL LIABILITY COVERAGE PART	\$	277.00
COMMERCIAL INLAND MARINE COVERAGE PART	\$	
	\$	
	\$	
es at melianes serves	\$	
DECEIVE	\$	As Invoiced
AUG 13-2009		
CONFIDENTIALINSTALLMENT SERV	ICE FEE S	32.00

FORMS APPLICABLE TO ALL COVERAGE PARTS:	710477	05/93	711081	02/03	*
711288 01/07 IL0017 11/98	IL0021	09/08	IL0250	09/08	

Provi	dia.	T mec	Sic coss	DECEMBER OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TO THE PERSON NAMED	1.0410	
8	2	99		Y	095	COUNTERSIGNED BY:  Authorized Representative
	The state of the s	A	L	4		LOUIS IN THE PROPERTY OF THE P

THESE DECLARATIONS TOGETHER WITH THE COMMON POLICY CONDITIONS, COVERAGE PART COVERAGE FORMIS). AND FORMS, IF ANY, ISSUED TO FORM A PART THEREOF, COMPLETE THE ABOVE NUMBERED POLICY.

FORM 71-0025 (ED. 03/91)

AGENCY

ISSUED 08/05/09

Hartford Insurance Company of the Midwest

Flood Insurance Processing Center P.O. Box 2057; Kalispell, MT 59903 - 2057 Wells Forgo Bank, H.A. P.O Box 88 Kalispell, MT 59903 wellstargo.com

THE ORIGINAL DOCUMENTAGES THE CONTROL OF THE SHORE THE VIEW WHEN THE WEST WAS THE FAMOUR SELVENT.

600539792

Ma. 600539792

AMOUNT

9/07/2010

***28,214,43

PAY

***28,214*AND*43/100*DOLLARS*

TO THE ORDER OF MAIL -

SOUTHERN UTILITY CORPORATION and TENNESSEE COMMERCE BANK

SOUTHERN UTILITY CORPORATION 180 COTTONWOOD LANE FRANKLIN, TN 37064

#O600539792# #O92905278# O196415343#

## Memorandum

To:

Jim Ford

CC:

From:

Scott Davis, Operations Manager

Date:

8/16/2011

Re:

Repair to Pumps, Motors, and Electrical Panels

Mr. Ford,

Berry's Chapel Utility, Inc. suffered severe damage to several pumps, motors, and electrical panels during the flood of May 2010. Many of the pumps and electrical panels were partially repaired and need full restoration to prevent future problems. Although, Southern Sales repaired many of the items needed, there are still many others that were never addressed due to the financial situation of BCUI. Listed below is a summary of the items that need to be addressed asap.

	Total	\$48,766.42
Pull motors and repair check valves		\$ 4,773.04
Completion of Electrical Composts/panels		\$ 8,130.80
Trailer Pump Station, brakes, starters, and overloads		\$ 5,373.00
Control Panel Repair and Bake and Bearing of motors		\$30,489.58

Thanks for your help in this matter,

Scott Davis

Operations Manager

		Lookup Job#	000-00	
WorkOrderNumber	☐ Bill to Job	Original Quote#	5056	
10925	Startup	Salesperson:	a phaghai yane Tan Samhir ishifi a ashiqiyo dimeridi 1984-1984 m40°	
I U J A. J	Project Warranty	Project Name:	kadilinah kermuni repikun andari SEE di SEE Belia keringa zaura kee kee kada kada di SEE	destantantus es sucres, anno en mones (y 3 septil)
	Service Warranty	Contractor:	in the state of the state of the similar of the similar of the state o	Shapharaco Median elicifornia anno respondenti discribita
	No Charge	City or Utility:	erit einem og up man fri i freder skurp skapenhellen som het skill skillen en uppensynsske mellem der det betæ	
anni pari	THE CONTRACTOR AND ADDRESS OF THE CONTRACTOR AND ADDRESS OF THE CONTRACTOR ADDRESS OF THE CONTRA	Engineer:	ing and the second of the seco	BD Stephingson billing in two minutes on a section
≅ Bill	to Customer	repartment of the control of the con		
Bill To:   Lynnwood L	Hilty Corp	Site Address Lynnwo	od	anthematika-man-k-nip-matterite-titleP
5250 Virgini Brentwood.	ia Way, Suite 100		Station at WWTP 5988-A	
blentwood.	114 07 02.7	Franklir		
g granistanassastanassastanassastanassastanassastanassastanassastanassastanassastanassastanassastanassastanass	nickson er store from historie och til de den de store foret foret som er store er som er store foret som er som e			COLUMN CONTROL AMONDO AND
Problem 05-06-10- (S Trouble sho	SD) ot and repair as needed for being ur	nder water		
- Anna				
al version and the second				
•		ganturanovenimusehumooteneeteleineteneetel	adala mendaga katigi mendanda dakatan data kepertendak kepertendak kepertendak dalam dalam dakan dakan dalam d	naceatth different new and which this state of signify
ContactPerson Tyler	Ring Call	lotes		ent
ContactPhone1 (615)	305-1033	Providence of the second		Application of the state of the
ContactPhone2	na na marana na manana na manan		and an industrial with the production production of the contract of the contra	AND TO SELECT AND THE PROPERTY OF THE PROPERTY
Qty Part Number	Description	Each Cost To	otal Cost Each Se	II Total Sell
		(1/2		
6 HOURS	STANDAJED LAB		96	3/6
1 607	Estimate To Retien	or the second of	and the second s	820
	INSTALL MOTOR			The second section of the contract of the cont
3 MOTHES	BAKED + BRATING	y and the second		1178.58
L Com	•			
Z	SOFT STAPTS REP	beent		25,385
and the second control of the second control	T. T. S.		_ / _ / who has have a second contract the sec	AND THE RESIDENCE OF A STATE OF THE PARTY AND ADDRESS OF THE PARTY AND
The state of the s	And the second s		a contract when the contract of	and the second s
Management of the security approximation of the security of th				<u>i</u> :
	4			
607	GSTIMATE CONTREL	& HOURS		JS00
	( MANNEC	)	*Programmed	
There is Alo	10001		2	1247458
- · · · · · · · · · · · · · · · · · · ·	+ Left ON		~ ~	
		FSTIMATE	のーク	, 101
This STATE		ESTIMATE	の一つ	0,489.58

	Dill 4a lab	Lookup Job #	000-00	
WorkOrderNumber	Bill to Job	Original Quote#	5056	
10887	Startup	Salesperson:	Eddal Andrick Construction of the Best Constru	
	Project Warranty	Project Name:	indentrologicus de specimente executivo con estator e con popular de nintrologica e con proposações de secutiv	onto a to de la company de
	Service Warranty	Contractor:	nerillähvesti vuon välidet yhde sinde sinytääpinkäikässa vään kyse yesse väästaksi sasjiye jäkasin vahetaa	constitutiva di prosperda fra menerica e submissioni successi di
	No Charge	City or Utility:	no filiti fina est kontinenti petro esi atronesi atripictor pia melopido poneto a applia desto, ellepti, escolado pel	erfelledistrotransk <del>er en mo</del> onierisropeeen
≅ Bil	I to Customer	Engineer:	a administrativam variaciti agravitete esti par esti para esti para esti para esti para esti participa de dell'	militaria suoti Salah Amerikkon meteoria mendisus (222 km).
5250 Virgi Suite 100	Utility Corp. nia Way	Site Address Lynwoo Franklin		ntakan telapung palmon ung prongsalis a <u>sasar</u>
Problem 05/03/10 II	nspect WWTP and repair as needed		namen and a superior and a little process and a finite constitute of the rate, and the public place in the language page.	BOTECON BERTON COMPANY PROCESS OF THE STATE
TO THE PROPERTY OF THE PROPERT				
designation				
ContactPerson Tyle	or Dian	otos I Plant Flooded	w Ballinanina ling Tennanan Kalenzan esin beberasa katalan epaten kain ne dente epatenta ya takan katalan kata Katalan katalan katala	egica ingipat-lang menekomengkanatalpang,
And a state of the	er Ring CallN 5) 305-1033	otes		
ContactPhone2	2) 202-1049			
		j		
ty Part Number	Description	Each Cost To	tal Cost Each Sell	Total Sell
Toves Hous	CONDUC LARGE ASSIST LABOR	e e e e e e e e e e e e e e e e e e e	96 66	677.07 313.50
<b>3</b>	Mary Brules		and the second s	1214,29
2	MOTOR STATTERS			23804
1 Lot	GUA PLUS FOR ABOVE			128,58
1	TRAILER Pump Right	4	e trans e tre en	
	MISC Electer PA			100%
•			The second secon	F. C.
	* · · · · ·		TO THE THE RESIDENCE OF THE PARTY OF THE PAR	and the same years
			e se servicio de la compansión de la compa	mana a sa
			The second decided	

I do not know what else is

Neco 60 Here.

		Disciplationage with particular security and particular security and particular security.
WorkOrderNumber	Bill to Job	Lookup Job # 000-00 Original Quote# 5056
10888	Startup	Salesperson:
	Project Warranty	Project Name:
	Service Warranty	Contractor:
	No Charge	City or Utility:
⁻ Bill	to Customer	Engineer:
Bill To: Lynwood U		Site Address Riverlanding PS
Suite 100 Brentwood	TN 37027	Franklin, TN
Problem   05/03/10 (SI		Station SN 99-5487-LP
CLODISTI 02/03/10 (2)	D) Inspect Flood Damage and repa	r as needed
The state of the s		
Management		
ContactPerson Tyler	Ring Call	Notes Can station Flooded
ContactPhone1 (615)	305-1033	
ContactPhone2	naminana kanana kan	
Qty Part Number	Description	Each Cost Total Cost Each Sell Total Sell
THE STATE OF THE S		
9.5 Hours	STANDARD LABOR	96 1008
	Assort LABOR	13) 1254
115	STANUAGO OT	144 216 , AROR
1,5	CONTROL OT ASSIST OT	198 297 LABOR 198 297 3451.
1 107	GR PACES For A	· · · · · · · · · · · · · · · · · · ·
LAOT	GR PATS For A GR CONTROL Parts	1236,50
2 moroes	Baren Bear my	692,86 Par
L. Lot.	electer Confuts	J.000.00 3879
	Estimate LABLE TO	800,a)
	Complete 8 Ms	The state of the s
		-01 ETE > 8730,8
_		OUTTE DO 10010

Estimate To COMPLETE > 8/50,0

For Tyler Insurprise	
	ookup Job # 000-00
WorkOrderNumber Bill to Job Or	iginal Quote# 5056
10951 Startup	Galesperson:
1	roject Name:
Service Warranty	Contractor:
No Charge C	ity or Utility:
Bill to Customer       —	Engineer:
Din to Customer	
5250 Virginia Way Suite 100	Address Lynwood UD - WWTP Main PS Franklin, TN
Problem 05/24/10 (SD) pull motor for repair and troubleshoot	main our me station
Flood Damage, check checkvalves	main pump station
ContactPerson Tyler Ring CallNotes  ContactPhone 1 (615) 305-1033	
ContactPhone2	
Qty Part Number Description	Each Cost Total Cost Each Sell Total Sell
	AND THE PARTY OF T
	The state of the s
3 des 2.75 Hes > 5.75 Hours Labor	00.622
	00.622
3.75 HRS > 5.75 How, Labor	1552.00 1534.52
1 TEM Abte Repair	1552.00 1834.52
1 TEM Able Repair	
1 TEM Abla Repair	
1 TEM Able Repair	
1 TEM Abla Repair	
1 TEM Abla Repair	
1 TEM Abba Repair	For one (2386.52
1 TEM Abla Repair	For one (2386.52